



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YM 8025L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR LH	DENTED	\$1,911.60	\$1,265.00
1	FRONT DOOR HINGE LH	BENT	\$121.00	\$121.00
1	FRONT DOOR HINGE (LOWER)	BENT	\$114.70	\$114.70
1	FRONT DOOR LH WINDOW FRAME MOULDING	NOT NECESSARY	\$90.00	\$0.00
1	FRONT DOOR WEATHERSTRIP LH	TORN	\$363.10	\$188.00
1	FRONT DOOR WEATHERSTRIP LH LOWER	TORN	\$140.30	\$140.30
1	FRONT DOOR GLASS REGULATOR LH	BENT	\$442.30	\$295.00
1	FRONT DOOR GLASS REGULATOR MOTOR LH	NOT NECESSARY	\$269.70	\$0.00
1	FRONT DOOR GLASS CHANNEL SEAL LH	NOT NECESSARY	\$146.90	\$0.00
1	FRONT DOOR GLASS CHANNEL BRACKET LH (FRONT)	NOT NECESSARY	\$120.20	\$0.00
1	FRONT DOOR GLASS CHANNEL BRACKET LH (REAR)	NOT NECESSARY	\$99.50	\$0.00
1	FRONT DOOR LH DOOR LAMP	NOT NECESSARY	\$245.00	\$0.00
1	FRONT DOOR CHECKER LH	NOT NECESSARY	\$165.80	\$0.00
1	FRONT DOOR TRIM BOARD LH	BENT	\$810.40	\$415.00
1	FRONT DOOR TRIM PLASTIC SEAL COVER	NOT NECESSARY	\$43.00	\$0.00
1	FRONT DOOR ARCH GARNISH LH	NOT NECESSARY	\$304.60	\$0.00
1	FRONT DOOR LH MIDDLE BLACK GARNISH	CUT	\$145.00	\$145.00
1	FRONT DOOR LOCK LH	NOT NECESSARY	\$155.00	\$0.00
1	FRONT DOOR LOCK MOTOR LH	NOT NECESSARY	\$210.00	\$0.00
1	FRONT STEP GARNISH LH	NOT NECESSARY	\$543.90	\$0.00
1	FRONT LH HEAD LAMP	BROKEN	\$810.00	\$442.00
1	FRONT LH SIGNAL LAMP	BROKEN	\$560.00	\$221.00
1	SIDE MIRROR	BENT	\$80.00	\$80.00
1	SIDE MIRROR BRACKET	BENT	\$130.00	\$130.00
1	FRONT BUMPER	BROKEN	\$640.00	\$425.00
1	FRONT BUMPER RH & LH	NOT NECESSARY	\$360.00	\$0.00
1	FRONT LH CORNER PANEL	BROKEN	\$235.00	\$235.00
1	FRONT LH CORNER PANEL GARNISH	NOT NECESSARY	\$45.00	\$0.00
	<b>LESS 15.00% DISCOUNT</b>		(\$1,395.30)	(\$632.55)
			<b>\$7,906.70</b>	<b>\$3,584.45</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT DOOR TRIM BOARD CLIP LH (SN)	NECESSARY	\$50.00	\$20.00
1	FRONT LH CORNER PANEL STICKER (SN)	NECESSARY	\$199.75	\$60.00
1	SET FRONT LH CORNER PANEL CLIPS (SN)	NECESSARY	\$60.00	\$15.00
			\$309.75	\$95.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN AFFECTED AREA		\$1,200.00	\$500.00
	TO SPRAY PAINT ON AFFECTED AREA		\$800.00	\$600.00
	TO REMOVE & REFIX DOOR MECHANISM & CHECK FOR FUNCTION		\$80.00	\$50.00
	TO CHECK WIRING, LAYOUT & CHECK FOR FUNCTION		\$100.00	\$30.00
	TO RUST PROOF AFFECTED AREA		\$80.00	\$30.00
			\$2,260.00	\$1,210.00
<b>GRAND TOTAL</b>			<b>\$10,476.45</b>	<b>\$4,889.45</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>\$3,900.00</b>
Report Ref No: CS/INC24060082/Eqh3e2				

TOTAL FOR SPARE PARTS: \$ 8,216.45 \$ 3,679.45  
TOTAL FOR LABOUR : \$ 2,260.00 \$ 1,210.00  
TOTAL REPAIR COST: \$ 10,476.45 \$ 4,889.45

**CTY**

STEVE CHEN TSUE YEE