

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070506/UPA3Q2**Date:** 15/11/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700005057  
**Claimant Vehicle No :** GBJ7502X **Insured Vehicle No :** SDA20P  
 Date of Loss: 29/07/2024 Nature of Claim: TP Claim No: 1642664875SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7502X**  
 Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEK (CBU) (M) Engine No: 4P10D75316  
 Reg. Date: 01/08/2019 (Man. Year: 2019) Chassis No: FEA01BA30208  
 Colour: White Odometer: 147299 km  
 Engine Capacity: 2998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)  
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6 mm  
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,949.00	1,538.75	1,410.25	47.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	1,050.00	290.00	21.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,289.00</b>	<b>2,588.75</b>	<b>1,700.25</b>	<b>39.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,289.00</b>	<b>2,050.00</b>	<b>2,239.00</b>	<b>52.20</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>2,452.18</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,450.00</b>		

INSPECTION

Date of Assignment: 01/08/2024  
 Date Inspected: 01/08/2024 Inspected At: Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)  
 Estimated Period of Repair: 4.0 days Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP (O/S CRACKED)(NOT CONSISTENT WITH THE IMPACT)	N/S Cracked	564.00 F	*282.00 FL
2	1		*REAR TAIL LAMP PANEL	N/S Bent / O/S Not Necessary	370.00 F	*185.00 FL
3	1		*REAR REVERSE SENSOR	Cracked	220.00 FS	*200.00 FS
4	1		*REAR NUMBER PLATE LAMP	Cracked	197.00 F	*148.00 FL
5	1		*REAR NUMBER PLATE METAL	Repair	28.00 F	*- FL
6	1		*REAR EXHAUST O2 SENSOR	Damaged / Torn	1,170.00 F	*1,170.00 FL
7	1		*REAR STEP PANEL	Repair	400.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,949.00</b>	<b>1,985.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	446.25
<b>Total Parts (\$\$)</b>	<b>2,949.00</b>	<b>1,538.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
2	REMOVE AND REPLACED REAR BUMPER REVERSE SENSOR	New	100.00	30.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	500.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,340.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >