



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: JOANNE TAN		Ref: CS/FCI24070507/Avp3e2(N) Date: 14/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 4483H	Veh. Inspected	FBE 2409S
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24006650MFCT	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	31/07/2024
2. Vehicle Particulars & Condition			
Make & Model	HONDA WAVE	c.c	125
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	NF125ST0029328	Colour	BLUE
Odometer	312847 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/80 R17	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/80 R17	MAXXIS	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/07/2024	Inspection Date	31/07/2024
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	