



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070511/Unp3
16 RAFFLES QUAY	Date:	14/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2450K	Veh. Inspected	FBR 6522C
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006477MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	31/07/2024

2. Vehicle Details

Make & Model	HONDA ADV150	C.C	149
Engine No.	KF61E1019656	Year of Reg.	15/09/2020
Chassis No.	MH1KF6116LK019687	Colour	WHITE
Odometer	37598 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110-80-14	PIRELLI	6
L/H Front Tyre			
R/H Rear Tyre	130-70-13	PIRELLI	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/07/2024	Inspection Date	31/07/2024
Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days