

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070512/KUA3Q2**Date:** 05/12/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100393422
Claimant Vehicle No :	SKS2686C	Insured Vehicle No :	GBD5288J
Date of Loss:	29/07/2024	Nature of Claim:	TP
		Claim No:	6786317098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS2686C		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Engine No:	1ZRX492055
Reg. Date:	02/04/2015 (Man. Year: 2015)	Chassis No:	MR053REH104527325
Colour:	Metallic Silver	Odometer:	315670 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,395.75	1,395.75	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	840.00	160.00	16.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,395.75	2,235.75	160.00	6.68
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	2,395.75	1,750.00	645.75	26.95
+ GST 9.00/9.00% (S\$)	215.62	157.50	58.12	26.95
Nett Amount (S\$)	2,611.37	1,907.50	703.87	26.95
+ Car Rental (3.0 x S\$90.00/day + 9.00% GST) (S\$)		294.30		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,203.98		

INSPECTION

Date of Assignment:	05/08/2024	
Date Inspected:	05/08/2024	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	870.30 FL	*870.30 FL
2	1		*FRONT GRILLE LOGO	Necessary	68.40 FL	*68.40 FL
3	4		*FRONT GRILLE CLIPS	Necessary	20.00 FL	*20.00 FL
4	1		*FRONT BUMPER	Buckled / Dented	878.30 FL	*878.30 FL
5	6		*FRONT BUMPER CLIPS	Necessary	24.00 FL	*24.00 FL
					Sub Total (S\$)	1,861.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	465.25
					Total Parts (S\$)	1,395.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ,GRILLE KNOCK & REPAIR FRT BUMPER REINFORCEMENT ,FRT SUPPORT PANEL AND REALIGN THE SAME	New	400.00	300.00
2	PUTTY & RESPRAY ON FRT BUMPER ,FRT BONNET ,SUPPORT PANEL	New	600.00	540.00
Gross Labour Cost (\$\$)			1,000.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >