



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKS 752H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	CUT	\$1,276.00	\$1,276.00
2	REAR BUMPER SENSOR @\$231.00	SHORTED	\$462.00	\$462.00
2	REAR BUMPER LAMP L+R @\$62.00	NOT NECESSARY	\$124.00	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$398.00	\$398.00
10	REAR BUMPER RIVETS @\$4.00	NECESSARY	\$40.00	\$40.00
1	REAR CAMERA (NPA)	NOT NECESSARY	\$0.00	\$0.00
	LESS 5.00% DISCOUNT		(\$115.00)	(\$108.80)
			\$2,185.00	\$2,067.20
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$35.00	\$0.00
			\$35.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPAIR REAR END PANEL, REAR BOOT, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS		\$350.00	\$250.00
	TO SPRAY REAR BOOT END PANEL, REAR BUMPER & AFFECTED AREAS		\$500.00	\$250.00
	TO DIAGNOSTIC & CHECK WIRING WHERE NECESSARY		\$120.00	\$60.00
			\$970.00	\$560.00
GRAND TOTAL			\$3,190.00	\$2,627.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$2,100.00
Report Ref No: CS/AGI24070513/Rnp3m4				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.