



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400505
INV Date : 30-10-2024

Reference CD/FCI24070515/Kua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 9618D
Insured Veh. SHC 3623Y
Claim No. D24006642MFCT/CTPL/JS
Policy No. D-24101861MFCT
Accident Date 27/07/2024
Inspection Date 31/07/2024

Description	Amount
Survey Inspection	250.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	250.00
GST (9%)	22.50
Grand Total	272.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070515/Kua3q2
16 RAFFLES QUAY	Date:	30/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHC 3623Y	Veh. Inspected	SHB 9618D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006642MFCT/CTPL/JS	Excess	\$0.00
Assign From	NEO JIE SI	Assign Date	31/07/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)	C.C	1798
Engine No.	2ZR2C35949	Year of Reg.	27/06/2019
Chassis No.	JTDKB3FU503082109	Colour	METALLIC PEARL WHITE/RED
Odometer	802982 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WANLI	4
L/H Front Tyre	195/65R15	WANLI	8
R/H Rear Tyre	195/65R15	DUNLOP	4
L/H Rear Tyre	195/65R15	DUNLOP	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/07/2024	Inspection Date	31/07/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHB 9618D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER ,REAR BUMPER	BUCKLED / CRACKED	\$558.39	\$558.39
1	COVER REAR BUMPER LOWER	CRACKED	\$19.43	\$19.43
1	GUARD ,REAR BUMPER CENTER	MTG DISTORTED	\$726.92	\$726.92
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	TO REPAIR SEE LABOUR	\$419.90	\$0.00
1	FILLER REAR BUMPER EXTENSION LH	MISSING	\$155.72	\$155.72
1	PANEL SUB-ASSY ,QUARTER LH	TO REPAIR SEE LABOUR	\$1,099.46	\$0.00
1	LINER ,REAR WHEEL HOUSE LH	SERVICEABLE	\$176.09	\$0.00
1	COVER ,FLOOR UNDER NO.1 LH	SERVICEABLE	\$220.50	\$0.00
1	COVER REAR COMBINATION LAMP LH	SERVICEABLE	\$81.48	\$0.00
1	LENS AND BODY ,REAR LAMP LH	SERVICEABLE	\$634.73	\$0.00
1	LENS & BODY REAR COMBINATION LAMP LH	CRACKED	\$559.13	\$559.13
	LESS 25.00% DISCOUNT		(\$1,162.94)	(\$504.90)
			\$3,488.81	\$1,514.69

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIP (SN)	NECESSARY	\$65.00	\$60.00
1	FENDER LINER CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
1	REAR TAIL LAMP CLIP (SN)	NOT NECESSARY	\$65.00	\$0.00
			\$195.00	\$60.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$250.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		\$1,800.00	\$500.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	NOT NECESSARY	\$380.00	\$0.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY REAR BUMPER AND PANEL SUB-ASSY QUARTER LH.		\$3,000.00	\$400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	NOT NECESSARY	\$220.00	\$0.00
	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	NOT NECESSARY	\$170.00	\$0.00
			\$5,990.00	\$920.00
GRAND TOTAL			\$9,673.81	\$2,494.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$2,000.00
Report Ref No: CD/FCI24070515/Kua3q2				

KSC

KENNETH KONG SENG CHEONG


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SHB 9618D



PHOTOGRAPHS FOR VEHICLE NO. : SHB 9618D



PHOTOGRAPHS FOR VEHICLE NO. : SHB 9618D



PHOTOGRAPHS FOR VEHICLE NO. : SHB 9618D

