

LKK Auto Consultants Pte Ltd (Co,Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 13 Jun 2024

Preliminary Advice

Vehicle No	: SNJ1278R	Accident Date	: 11/06/2024
Make	: BMW 528I	Policy No.	: MPC24P00082100
Assignment Date	: 13/06/2024	Excess	: S\$350.00
Date of Inspection	: 13/6/2024	Est. Duration of Repair	: 5
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,317.70
Revised Amount	:S\$	9,633.70
Check Items (Estimated)	:S\$	12,547.70
Total	:S\$	22,181.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	126,000.00
COE / PARF Rebate	:S\$	93,925.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,075.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Part by part repair.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .

According to surveyor, no modification found.At the time of inspection, steering, brake are in order, all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately front 6mm and rear 8mm.

According to repairer, insured insist to see all new parts.