

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24080002/Unh3	
	75 BRAS BASAH R		Date:	12/08/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.		Policy Particulars :- THIRD PARTY CLAIM			
••	Insured Veh.	SMW 5066C	Veh. Inspected	SLM 5032P	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1288263-002	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	01/08/2024	
2.	Vehicle Details				
	Make & Model	SUBARU OUTBACK (A)	C.C	2498	
	Engine No.	FB25Y476729	Year of Reg.	31/03/2017	
	Chassis No.	JF2BS9KC2GG044144	Colour	GREY	
	Odometer	121866 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/60R18	BRIDGESTONE	6	
	L/H Front Tyre	225/60R18	BRIDGESTONE	6	
	R/H Rear Tyre	225/60R18	BRIDGESTONE	6	
	L/H Rear Tyre	225/60R18	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.		General Information			
	Accident Date	27/07/2024	Inspection Date	06/08/2024 (10:22)	
	Survey held at	SD CAR CARE CENTRE 2 KAKI BUKIT AVENUE 2 #01-29 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days