



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 7566C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BADGE	NOT NECESSARY	65.00	-
1	BADGE MODEL	NOT NECESSARY	50.00	-
1	CONTROL ROD	BENT	315.00	315.00
1	ENGINE FIREWALL	* CHECK	650.00	-
1	FRONT AXLE (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER	TORN	395.00	395.00
1	FRONT PANEL	NOT NECESSARY	530.00	-
1	FRONT TIE ROD (NPA)	NOT NECESSARY	-	-
1	FRT CONNECT PNL SEAL (NPA)	NOT NECESSARY	-	-
1	FRT LWR BUMPER REINF (NPA)	NOT NECESSARY	-	-
1	FRT SCREEN MNTG KIT (NPA)	NOT NECESSARY	-	-
1	FRT UPP BUMPER REINF (NPA)	NOT NECESSARY	-	-
1	GRILLE	NOT NECESSARY	380.00	-
1	HORN	NOT NECESSARY	110.00	-
1	L/F BUMPER BRACKET	BENT	200.00	200.00
1	LEFT HEADLAMP ASSY	NOT NECESSARY	590.00	-
1	OUTER ENG FIREWALL (NPA)	NOT NECESSARY	-	-
1	R/DOOR FRAME TRIM	* CHECK	65.00	-
1	R/DOOR MIRROR ASSY	NOT NECESSARY	135.00	-
1	R/DOOR SEAL	NECESSARY	140.00	140.00
1	R/END MOULDING	* CHECK	165.00	-
1	R/F BUMPER BRACKET	BENT	200.00	200.00
1	R/F COVER PANEL	CRACKED	120.00	120.00
1	R/F DOOR CHECK	* CHECK	105.00	-
1	R/F DOOR FRAME SEAL	NECESSARY	125.00	125.00
1	R/F DOOR OUT HANDLE	NOT NECESSARY	125.00	-
1	R/F DOOR TRIM (NPA)	NOT NECESSARY	-	-
1	R/F INN D/TRIM COVER	* CHECK	60.00	-
1	R/F INN WHEEL BRG	* CHECK	65.00	-
1	R/F LOWER DOOR HINGE	* CHECK	75.00	-
1	R/F MUDFLAP (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/CTI24080003/Rqh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/F OUT WHEEL BRG	* CHECK	65.00	-
1	R/F PRESSURE VALVE	* CHECK	20.00	-
1	R/FR SHOCK ABSORBER	* CHECK	135.00	-
1	R/FR TYRE	CUT	300.00	300.00
1	R/FR WHEEL	BENT	500.00	500.00
1	R/F ST/BOARD BRK FRT (NPA)	NOT NECESSARY	-	-
1	R/F STEERING ARM	* CHECK	165.00	-
1	R/F STEERING KNUCKLE	* CHECK	500.00	-
1	R/F STEP	MISSING	185.00	185.00
1	R/F SUPPORT BRACKET	* CHECK	500.00	-
1	R/F UPPER DOOR HINGE	NOT NECESSARY	75.00	-
1	R/F WHEELHOUSE COVER	NOT NECESSARY	195.00	-
1	R/INN DOOR LOCK	NOT NECESSARY	155.00	-
1	R/LOWER DRIP RAIL (NPA)	NOT NECESSARY	-	-
1	R/MOULDING SEAL	* CHECK	25.00	-
1	R/OUTER A-PILLAR	TO REPAIR SEE LABOUR	500.00	-
1	R/R DOOR STRIKER	NOT NECESSARY	65.00	-
1	R/R REINFORCEMENT	* CHECK	105.00	-
1	R/RR WHEEL	BENT	500.00	500.00
1	R/SIDE REINFORCEMENT	TO REPAIR SEE LABOUR	125.00	-
1	R/WHEEL HUB COVER	NOT NECESSARY	65.00	-
1	R/WINDOW CHANNEL	NOT NECESSARY	140.00	-
1	RIGHT FRONT DOOR	BENT	950.00	950.00
1	RIGHT HEADLAMP ASSY	BROKEN	590.00	590.00
1	SHIFT LINKAGE	* CHECK	575.00	-
1	WASHER RESERVOIR	NOT NECESSARY	120.00	-
1	WASHER RESERVOIR CAP	NOT NECESSARY	25.00	-
1	WASH RESERVOIR TUBE	NOT NECESSARY	40.00	-
1	WINDSCREEN BOND KIT (NPA)	NOT NECESSARY	-	-
1	WINDSCREEN SEAL (NPA)	NOT NECESSARY	-	-
1	W-SCREEN WASHER PUMP	NOT NECESSARY	145.00	-
			11,430.00	4,520.00

Report Ref No. CS/CTI24080003/Rqh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	CTP SUNDRIES (SN)	NECESSARY	30.00	20.00
1	CTP SEALANT (SN)	NECESSARY	25.00	20.00
1	NUMBER PLATE (SN)	BENT	35.00	35.00
			90.00	75.00
	<u>LABOUR</u>			
	CTP ELECTRICAL.		25.00	25.00
	DIAGNOSE FAULT CODE.		200.00	150.00
	CTP WHEEL ALIGNMENT.		60.00	60.00
	CTP AIR-CON.	NOT NECESSARY	50.00	-
	TOTAL 409.0 WU X 42.00 SGD/H. INCLUSIVE OF THE REPAIR OF R/OUTER A-PILLAR AND R/SIDE REINFORCEMENT.		1,717.80	1,717.80
	MEASURING WORK.		29.40	29.40
	LABOUR COST 95.0 WU X 42.00 SGD/H.		399.00	399.00
	MATERIAL COST.		115.39	115.39
			2,596.59	2,496.59
	GRAND TOTAL		14,116.59	7,091.59

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$3,275.00 NETT)			7,091.59
LESS EXCESS			-350.00
NETT LIABILITY			6,741.59

Report Ref No. CS/CT124080003/Rqh3m4(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.