

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080004/KPA3Q2**Date:** 18/11/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070175925
Claimant Vehicle No : SBT12L **Insured Vehicle No :** SLU8889Y
Date of Loss: 27/07/2024 Nature of Claim: TP Claim No: 9022407714SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBT12L**
Make & Model: TESLA MODEL 3 PERFORMANCE, (A) Engine No: HIDDEN
Reg. Date: 10/11/2021 (Man. Year: 2021) Chassis No: LRW3F7EL7MC282999
Colour: Grey Odometer: 52206 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R20 Rear Tyre Size: 245/35 R20
Front Left Side: Giti 9 mm Rear Left Side: Giti 9 mm
Front Right Side: Giti 9 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,043.10	1,799.19	243.91	11.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,680.00	860.00	33.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,583.10	3,479.19	1,103.91	24.09
+ GST 9.00/9.00% (S\$)	412.48	313.13	99.35	24.09
Nett Amount (S\$)	4,995.58	3,792.32	1,203.26	24.09
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		4,250.57		
Global Sum Settlement (S\$)		4,250.00		

INSPECTION

Date of Assignment: 01/08/2024
Date Inspected: 01/08/2024 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Buckled / Dented	766.00 FL	*766.00 FL
2	1		*RR BUMPER LHS REFLECTOR	Cracked	20.56 FL	*20.56 FL
3	1		*RR REINFORCEMENT BAR	Repair	271.02 FL	*- FL
4	1		*RR BOOT	Bent	728.97 FL	*728.97 FL
5	1		*RR BOOT EMBLEM LOGO	Necessary	37.38 FL	*37.38 FL
6	1		*RR BOOT EMBLEM DUAL MOTOR	Necessary	29.90 FL	*29.90 FL
7	1		*RR LOWER BUMPER	Cut	140.18 FL	*140.18 FL
8	1		*RR BUMPER UNDERCOVER	Distorted	205.60 FL	*205.60 FL
9	1		*RR BUMPER HITCH COVER	Missing	14.95 FL	*14.95 FL
10	1		*RR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,264.56	1,993.54
- List Item Discount on L Items 10.00/10.00% (\$\$)	221.46	194.35
Total Parts (\$\$)	2,043.10	1,799.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CAR WRAP	New	850.00	800.00
2	TO REMOVE ,REPLACE ,REPAIR ,READJUST & REFIX RR AFFECTED AREAS	New	800.00	400.00
3	TO PERFORM WIRING CHECK ON ELECTRICAL SYSTEMS	New	30.00	20.00
4	TO REMOVE ,PUTTY ,REPAIR ,SAND AND RESPRAY AFFECTED AREAS	New	600.00	400.00
5	TO REMOVE,REPLACE & REFIX BUMPER SENSORS	New	30.00	30.00
6	TO REMOVE,REPLACE & REINSTALL BOOTLID INNER MECHAMISM	New	30.00	30.00
7	TO PERFORM ADAS CHECKS ,CALIBRATION & PROGRAMMING	New	200.00	0.00
Gross Labour Cost (\$\$)			2,540.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >