10/17/24, 2:54 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080005/RUA3Q2

Date: 17/10/2024

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372\_03

**Claimant Vehicle** SBS3407S Insured Vehicle No: SHD2652P

No:

Date of Loss: 28/07/2024 Nature of Claim: ΤP Claim No: MFL2024D0009047

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SBS3407S Reg No:

VOLVO B9TL, 9.4 D AUTO TURBO ABS (A) Make & Model: Engine No: D9192908

YV3S4P923EA167613 Reg. Date: 01/08/2014 (Man. Year: 2014) Chassis No:

Colour: Green Odometer: 653724 km

**Engine Capacity:** 9364 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

**CONDITION OF TYRES** 

Front Tyre Size: 275/70 R22.5 275/70 R22.5 (D) Rear Tyre Size: Front Left Side: Rear Left Side: Bridgestone 8 mm Bridgestone 8/8 mm Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,300.67	9,300.67	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,600.00	6,470.00	7,130.00	52.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,900.67	15,770.67	7,130.00	31.13
+ GST 9.00/9.00% (S\$)	2,061.06	1,419.36	641.70	31.13
Nett Amount (S\$)	24,961.73	17,190.03	7,771.70	31.13

+ Loss of Use (11.0 x S\$200.00/day) (S\$) 2,200.00

**(S\$)** 19,390.03

Liable Amount (50.00%) (S\$) 9.695.02

**INSPECTION** 

Date of Assignment: 01/08/2024

Tower Transit Singapore Pte Ltd (HQ) Date Inspected: 01/08/2024 Inspected At: 21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair: 10.0 days

MOHD RASUL Adjuster: NA MENG YAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/17/24, 2:54 PM Adjuster Report

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Sep 2024)

Parts: N/A VOLVO B9TL 9.4 D AUTO TURBO ABS (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS3407S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty P	art No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Broken	1,407.87 F	*1,407.87 F
2	1		*FRONT BUMPER LOCK ME	Bent	1,353.42 F	*1,353.42 F
3	1		*NS CORNER BUMPER	Cracked	429.00 F	*429.00 F
4	1		*LOWER DECK FRONT DOME	Cracked	4,905.32 F	*4,905.32 F
5	1		*MID BUMPER FRONT (OLD)	Cracked	361.83 F	*361.83 F
6	1		*NS DEFLECTOR	Cracked	176.00 F	*176.00 F
7	1		*OS W PART CHROME PLATED ABS	Necessary	86.48 F	*86.48 F
8	1		*FRONT W LOGO	Necessary	256.43 F	*256.43 F
9	1		*W MIDDLE PART CHROME PLATED ABS	Necessary	129.16 F	*129.16 F
10	1		*VOLVO SMALL LOGO 192X26MM	Necessary	129.16 F	*129.16 F
11	1		*TOWER TRANSIT LOGO (S)	Necessary	66.00 F	*66.00 F
r=Fra	inchise par	π.		Total Parts (S\$)	9,300.67	9,300.67

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO DISMANTLE & REPLACE : DISMANTLE AND REPLACE ITEM NO :1 11 }	- New	7,150.00	4,550.00				
2	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS : FRONT DOME, FRONT WINDSCREEN GLASS, FRONT BUMPER LOCK ,NS CORNER BUMPER, MID BUMPER }		3,250.00	0.00				
3	SPRAY PAINTING:FRONT DOME,FRONT WINDSCREEN GLASS,FRONT BUMPER LOCK,NS CORNER BUMPER,MID BUMPER	Γ New	3,200.00	1,920.00				
	Gross Labour Cost (S\$)		13,600.00	6,470.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >