

ESTIMATE FOR SFJ3399G

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 6 RAFFLES QUAY #21-00 SINGAPORE 048580 65073848

Vehicle & Document Information

WIP No 19695

Reg No/Reg Date

SFJ3399G / 21/01/2015

Date In/Mileage

Chassis No

-11000 WDD2120362B089591

Engine No.

27492030301040

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

027 775 Iridium sil/ 042 274 Leather Jav

Colour/Trim Account No Terms Date/Time Printed CSE Operator WF001862 Credit 27/07/2024/ 10:49 301 / Kerlyn Ong Description of Goods / Services Qty Unit Price Disc% Amount Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : // 26/07/2024 DRIVE IN/TP VEHICLE NO. : 27/07/2024 // SH7744Z - FIRST CAPITAL DATE IN/DATE SURVEY: BY/AUTHRIZED ON A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. A BPIRES RESPRAY REAR BUMPER A BPILAB 0.10 380.00 USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD, NETT 120.00 A BPILAR CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT 15.00XW M BPNSUN SUNDRY REAR BUMPER de 1.00 1837.82 00.00 1837.82 / REAR BUMPER LOWER TRIM ? (A) 1.00 292.43 00.00 292.43 LH/ REAR BUMPER CHROME MOULDING de / 209.84 00.00 1.00 209.84/ RH/ REAR BUMPER CHROME MOULDING . -1.00 209.84 00.00 209.84/ 201-17 402.34 2.00 201.17 00.00 REAR DISTANCE SENSOR MIT. 2.00 00.00 17.78/ 8.89 SPACER RING AL LH/ BASIC MOUNTING FOR BUMPER ? KALL 1.00 72.53 00.00 72.53 49.85 49.85 00.00 1.00 32.64/ 32.64 00.00 LH/ REAR BUMPER BOTTOM BRACKET ". N-/ 1.00 LKK Auto Consultants hence notify the Repairer of the following: · To resurvey before/after spray painting To display-damaged part(s) during resurvey Parts prices are subject to confirmation . Third party survey is on a "Without Prejudice" basis · No illegal codification six allowed 6,760.07 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Nett Kerlyn Ong Kai Li 608.41 6760.07 9% GST on DID: 6771 4420 HP: 9186 5113 Email: kerlyn.ong@cyclecarriage.com.sg Acknowledged by Repairer 7,368.48

ustomer Service Centre - Pandan Loop Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur. we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.


Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

Total Payable



Authorized signatory and company stamp



ESTIMATE FOR SFJ3399G

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 6 RAFFLES QUAY #21-00 SINGAPORE 048580 65073848

Vehicle & Document Information WIP No

19695

Reg No/Reg Date SFJ3399G / 21/01/2015

Date In/Mileage

25/09/2024/ 65070

Chassis No

WDD2120362B089591 27492030301040

Engine No Make/Model

MB/E 250 2.0 CGI SEDAN (W212

027 775 Iridium sil/ 042 274 Leather Jav Colour/Trim

Account No Terms Date/Time Printed CSE Operator WF001862 Credit

01/10/2024/ 10:04 KO 301 / Kerlyn Ong

Description of Goods / Services

Qty

Unit Price Disc%

Amount

RH/ REAR BUMPER BOTTOM BRACKET AL

28.21 00.00 1.00 28.21

STIMATE

SUPPLEMENTARY

Confirmed & accepted by

T

hor of t

cost

ter vise must of ti

Nett 9% GST on 28.21

Total Payable

28.21 2.54

30.75

Authorized signatory and company stamp

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has Commenced. Occasionally more of the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has Commenced. Occasionally more of the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after your parts of the same cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the recoval of the windscreen. the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 ww.mercedes-benz.com.sg