

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24080007/EQP3M4**Date:** 10/09/2024REFERENCE

Insured/Claimant: LIM SEE HUIV Policy No: MPC24A00240400
Date of Loss: 28/07/2024 Nature of Claim: OD Claim No: DMPC2400977H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNQ8395C**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A) Engine No: 1ZR0H43571
Reg. Date: 09/11/2021 (Man. Year: 2021) Chassis No: MR2BE3BE800016508
Colour: Blue Odometer: 47044 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$113,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,626.00	320.10	3,305.90	91.17
Miscellaneous Items	235.00	85.00	150.00	63.83
Paintwork Materials	300.00	0.00	300.00	100.00
Labour	1,470.00	200.00	1,270.00	86.39
Paintwork Labour	720.00	200.00	520.00	72.22
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,351.00	805.10	5,545.90	87.32
+ GST 9.00/9.00% (S\$)	571.59	72.46	499.13	87.32
Nett Amount (S\$)	6,922.59	877.56	6,045.03	87.32

INSPECTION

Date of Assignment: 01/08/2024 Present Location: Dickson Auto Care Centre Pte Ltd (HQ)
Date Inspected: 02/08/2024 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)
Estimated Period of Repair: 3.0 days 29 Ubi Road 4, Dickson Auto Centre
Singapore 408619

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ8395C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air-cond condenser (WCP)	Not Necessary	370.00 F	*- F
2	1		Bumper bracket LH, front (WCP)	Not Necessary	30.00 F	*- F
3	1		Bumper bracket RH, front (WCP)	Not Necessary	30.00 F	*- F
4	10		Bumper clip, front (WCP)	Not Necessary	18.00 F	*- F
5	1		Bumper reinforcement, front (WCP)	Not Necessary	150.00 F	*- F
6	1		Bumper, front (WCP)	Repair	235.00 F	*- F
7	1		Headlamp LH (WCP)	Not Necessary	680.00 F	*- F
8	1		Headlamp RH (WCP)	Not Necessary	680.00 F	*- F
9	1		Panel, front (WCP)	Not Necessary	540.00 F	*- F
10	1		Radiator (WCP)	Not Necessary	300.00 F	*- F
11	1		Radiator grille (WCP)	Broken	150.00 F	*150.00 F
12	10		Radiator grille clip (WCP)	Necessary	18.00 F	*6.00 F
13	1		*Radiator air deflector LH (WCP)	Not Necessary	80.00 F	*- F
14	1		*Radiator air deflector RH (WCP)	Not Necessary	80.00 F	*- F
15	1		*Bumper Front Shock Absorber Foam (WCP)	Not Necessary	50.00 F	*- F
16	1		*Bumper Front Undercover (WCP)	Not Necessary	55.00 F	*- F
Supplementary #1						
17	1		*Bumper Lower Grille (WCP)	Broken	135.00 F	*135.00 F
18	1		*Bumper Front Retainer Lower (WCP)	Not Necessary	25.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	3,626.00	291.00
+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00	29.10
Total Parts (\$\$)	3,626.00	320.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Materials				
1	1	Paintwork Materials	300.00	0.00
Miscellaneous Items				
2	1	Air-cond gas (R134A) Not Necessary	60.00	0.00
3	1	Electronic diagnosis Necessary	60.00	30.00
4	1	Number plate front holder Cut	40.00	30.00
5	1	Number plate, front Bent	25.00	25.00
6	1	Radiator coolant Not Necessary	30.00	0.00
7	1	Underseal materials Not Necessary	20.00	0.00
Sub Total (\$\$)			535.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Bumper, front	New	300.00	200.00
2	Bumper reinforcement, front	New	120.00	0.00
3	Panel, front	New	300.00	0.00
Labour Items				
4	Bumper bracket, front }	New	40.00	200.00
5	Bumper, front }	New	300.00	0.00
6	Radiator }	New	250.00	0.00
7	Air-cond condenser }	New	150.00	0.00
8	Bumper reinforcement, front }	New	120.00	0.00
9	Headlamp LH }	New	80.00	0.00
10	Headlamp RH }	New	80.00	0.00
11	Panel, front }	New	450.00	0.00
Gross Labour Cost (\$\$)			2,190.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >