

Dickson Auto Care Centre Pte Ltd (Co.Reg.No:201921404K)

29 Ubi Road 4, Dickson Auto Centre

Singapore 408619

Tel: 6668 1122 Fax: 6668 1123 Email: admin@dacc.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24A00240400	Date of Loss:	28/07/2024
Vehicle Reg. No.:	SNQ8395C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM SEE HUIV	Contact No:	+6596790843
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 ELEGANCE 2WD (A)	Vehicle Reg. Date:	09/11/2021
Vehicle Colour:	METALLIC BLUE	Chassis No:	MR2BE3BE800016508
Engine No:	1ZR0H43571		
Odometer:	46874 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	DICKSON AUTO CARE CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,466.00
Miscellaneous Items	235.00
Paintwork Materials	300.00
Labour	1,470.00
Paintwork Labour	720.00
Flowing	0.00
Gross Total (\$\$)	6,191.00
+ GST 9.00% (\$\$)	557.19
Nett Amount (\$\$)	6,748.19

This claim is handled by: MIRA / XIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Jul 2024)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Dickson Auto Care Centre Pte Ltd/SNQ8395C/31/07/2024 16:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air-cond condenser <i>Y nn</i>	0.00	0.00	*370.00 F
2	1		Bumper bracket LH, front <i>Y nn</i>	0.00	0.00	*30.00 F
3	1		Bumper bracket RH, front <i>Y nn</i>	0.00	0.00	*30.00 F
4	10		Bumper clip, front <i>Y nn</i>	0.00	0.00	*18.00 F
5	1		Bumper reinforcement, front <i>Y nn</i>	0.00	0.00	*150.00 F
6	1		Bumper, front <i>Y R (To dismantle check)</i>	0.00	0.00	*235.00 F
7	1		Headlamp LH <i>Y nn</i>	0.00	0.00	*680.00 F
8	1		Headlamp RH <i>Y nn</i>	0.00	0.00	*680.00 F
9	1		Panel, front <i>Y nn</i>	0.00	0.00	*540.00 F
10	1		Radiator <i>Y nn</i>	0.00	0.00	*300.00 F
11	1		Radiator grille <i>BR (supp)</i>	0.00	0.00	*150.00 F /
12	10		Radiator grille clip <i>BR</i>	0.00	0.00	*18.00 F 6 /
13	1		*Radiator air deflector LH <i>Y nn</i>	0.00	0.00	*80.00 F
14	1		*Radiator air deflector RH <i>Y nn</i>	0.00	0.00	*80.00 F
15	1		*Bumper Front Shock Absorber <i>Y nn</i>	0.00	0.00	*50.00 F
			Foam			
16	1		*Bumper Front Undercover <i>Y nn</i>	0.00	0.00	*55.00 F
Total Parts (\$\$)						3,466.00

F=Franchise part.

Dickson Auto Care Centre Pte Ltd/SNQ8395C/31/07/2024 16:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

(Supp)
front Bumper lower grille - BR

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Materials</u>		
1	1 Paintwork Materials (Refer paintwork letter)	X 300.00
<u>Miscellaneous Items</u>		
2	1 Air-cond gas (R134A)	nn X 60.00
3	1 Electronic diagnosis	net 30/ 60.00
4	1 Number plate front holder	net 30/ 40.00
5	1 Number plate, front	BT / 25.00
6	1 Radiator coolant	nn X 30.00
7	1 Underseal materials	nn X 20.00
85	Sub Total (\$)	535.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Bumper, front	New Spray 200	300.00
2	Bumper reinforcement, front	New X ?	120.00
3	Panel, front	New X	300.00
<u>Labour Items</u>			
4	Bumper bracket, front	New Labour	40.00
5	Bumper, front	New 200	300.00
6	Radiator	New	250.00
7	Air-cond condenser	New	150.00
8	Bumper reinforcement, front	New	120.00
9	Headlamp LH	New	80.00
10	Headlamp RH	New	80.00
11	Panel, front	New	450.00
400	Gross Labour Cost (\$)		2,190.00

Dickson Auto Care Centre Pte Ltd/SNQ8395C/31/07/2024 16:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)
2/8/24, 11.00am
OD-N-1 AL
Excess - ?
PIP
R1 B/L sy
3 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: