

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080008/KQP3E2**Date:** 07/10/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKK7506Z **Insured Vehicle No :** SLN7058Y

Date of Loss: 26/07/2024 Nature of Claim: TP Claim No: DMPC2400965H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK7506Z**

Make & Model: TOYOTA PREMIO, 1.5 F (A) Engine No: 1NZD506147

Reg. Date: 25/09/2009 (Man. Year: 2009) Chassis No: NZT2603051874

Colour: Metallic Brown Odometer: 169533 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14

Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,068.02	3,376.02	692.00	17.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	830.00	890.00	51.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,788.02	4,206.02	1,582.00	27.33
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	5,788.02	3,350.00	2,438.02	42.12
+ GST 9.00/9.00% (S\$)	520.92	301.50	219.42	42.12
Nett Amount (S\$)	6,308.94	3,651.50	2,657.44	42.12

INSPECTION

Date of Assignment: 31/07/2024

Date Inspected: 12/08/2024 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2024)
Parts:	143	TOYOTA PREMIO 1.5 F (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK7506Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,536.80 FL	*1,536.80 FL
2	1		*REAR BOOT EMBLEM	Necessary	84.10 FL	*84.10 FL
3	1		*REAR BOOT PREMIO LOGO	Necessary	83.40 FL	*83.40 FL
4	1		*REAR BOOT LAMP LH	Cracked	385.10 FL	*385.10 FL
5	1		*REAR BUMPER	Buckled	2,282.80 FL	*2,282.80 FL
6	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	175.00 FL	*- FL
7	1		*REAR BUMPER CLIPS (15PCS)	Necessary	82.50 FL	*82.50 FL
8	1		*REAR END PANEL	Repair	481.00 FL	*- FL
9	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
10	1		*SET REVERSE SENSOR	No such part	200.00 FS	*- FS
					Sub Total (S\$)	5,345.70 4,489.70
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,277.68 1,113.68
					Total Parts (S\$)	4,068.02 3,376.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
2	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
3	TO SPRAY REAR BOOT, REAR BUMPER, END PANEL	New	800.00	400.00
4	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS	New	60.00	0.00
Gross Labour Cost (S\$)			1,720.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >