8/19/24, 1:47 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd

Our File No:

CS/III24080012/UNP3E2

6 Raffles Quay, #22-00 Singapore 048580

Date:

19/08/2024

REFERENCE

Date of Loss:

Insured/Claimant:

Chua Hood Kiat Anthony

Policy No: Nature of Claim: D20MPC0005258

OD

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SBX72S

30/07/2024

Make & Model:

MAZDA CX-3, 1.5 CLASSIC I3.5 (A)

Engine No: Chassis No: PE31269400

Reg. Date:

31/08/2018 (Man. Year: 2018)

Odometer:

JM6DK2W7AK0406050 105224 km

Engine Capacity: Market Value/New Car 1998 cc

Price:

S\$62,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** No Yes

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 225/45 R16 Firenza 6 mm Firenza 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/45 R16 Firenza 6 mm

Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,293.10	3,693.78	1,599.32	30.22
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,130.00	1,620.00	1,510.00	48.24
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,423.10	5,313.78	3,109.32	36.91
	Approved Total (Overridden) (S\$)		4,200.00		
	- Excess (S\$)	750.00	750.00	0.00	0.00
	Nett Amount (S\$)	7,673.10	3,450.00	4,223.10	55.04

INSPECTION

Date Inspected:

Adjuster:

Date of Assignment:

01/08/2024

02/08/2024

Inspected At:

Hup Motor Trading & Service (HQ)

Blk 9004 Tampines Street 93, #01-120

Singapore 528838

Estimated Period of Repair:

5.0 days

MARCUS CHUA

Manager:

HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/19/24, 1:47 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Aug 2024)

Parts: M1-SUV MAZDA CX-3 1.5 CLASSIC I3.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBX72S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	1,193.15 FL	*1,193.15 FL
2	10		*REAR BUMPER CLIPS	Necessary	57.10 FL	*57.10 FL
3	1		*REAR BUMPER O/S TOP RETAINER	Cracked	26.30 FL	*26.30 FL
4	1		*REAR BUMPER O/S SIDE RETAINER	Cracked	26.81 FL	*26.81 FL
5	1		*REAR BUMPER CENTRE LOWER GARNISH	Grazed	148.87 FL	*148.87 FL
6	1		*REAR BUMPER O/S REFLECTOR	Not Necessary	174.81 FL	*- FL
7	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	369.18 FL	*- FL
8	1		*O/S TAIL LAMP ASSY LED	Cracked	2,192.62 FL	*1,650.20 FL
9	2		*O/S TAIL LAMP CLIPS STOPPER	Not Necessary	11.42 FL	*- FL
10	1		*REAR O/S FENDER	Badly Dented / Buckled	1,242.88 FL	*1,242.88 FL
11	6		*REAR O/S FENDER INNER SHIELD CLIPS	Necessary	34.26 FL	*34.26 FL
12	1		*REAR O/S FENDER QUARTER GLASS SEAL	Necessary	36.71 FL	*36.71 FL
13	1		*REAR O/S FENDER QUARTER GLASS INNER DAMPER	Necessary	39.61 FL	*39.61 FL
14	1		*REAR O/S WHEEL GUARD GARNISH	Distorted	86.67 FL	*86.67 FL
15	10		*REAR O/S WHEEL GARNISH CLIPS & STOPPER	Not Necessary	57.10 FL	*- FL
16	1		*REAR O/S WHEEL GARNISH BRACKET	Twisted	37.17 FL	*37.17 FL
17	1		*REAR O/S SPORT RIM	Repair	821.71 FL	*- FL
18	1		*REAR O/S FENDER QUARTER GLASS SEALANT	Necessary	48.00 FS	*30.00 FS
⊢=⊢ra	anchise	part. S=Spo	Nett. L=ListItemDisc.	Cub Tatal (CC)	C CO4 27	4 000 72
				Sub Total (S\$)	6,604.37	4,609.73

Sub Total (S\$) 6,604.37 4,609.73
- List Item Discount on L Items 20.00/20.00% (S\$) 1,311.27 915.95

Total Parts (S\$) 5,293.10 3,693.78

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR O/S FENDER QUARTER GLASS & NECESSARY	New	150.00	60.00
3	TO REMOVE & REFIX CUSHION SEAT, CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, TOOL SET, SPARE TYRE & NECESSARY PARTS	New	180.00	80.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,350.00	600.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS,TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,250.00	800.00
	Gross Labou	r Cost (S\$)	3,130.00	1,620.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >