

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III24080012/UNP3E2**Date:** 19/08/2024REFERENCE

Insured/Claimant:	Chua Hood Kiat Anthony	Policy No:	D20MPC0005258	
Date of Loss:	30/07/2024	Nature of Claim:	OD	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBX72S		
Make & Model:	MAZDA CX-3, 2.0 DELUXE 2WD (A)	Engine No:	PE31269400
Reg. Date:	31/08/2018 (Man. Year: 2018)	Chassis No:	JM6DK2W7AK0406050
Colour:	Grey	Odometer:	105224 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R16	Rear Tyre Size:	225/45 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,293.10	3,693.78	1,599.32	30.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,620.00	1,510.00	48.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,423.10	5,313.78	3,109.32	36.91
Approved Total (Overridden) (\$\$)		4,200.00		
- Excess (\$\$)	750.00	750.00	0.00	0.00
Nett Amount (\$\$)	7,673.10	3,450.00	4,223.10	55.04

INSPECTION

Date of Assignment:	01/08/2024		
Date Inspected:	02/08/2024	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Aug 2024)	
Parts:	N/A	MAZDA CX-3 2.0 DELUXE 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBX72S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	1,193.15 FL	*1,193.15 FL
2	10		*REAR BUMPER CLIPS	Necessary	57.10 FL	*57.10 FL
3	1		*REAR BUMPER O/S TOP RETAINER	Cracked	26.30 FL	*26.30 FL
4	1		*REAR BUMPER O/S SIDE RETAINER	Cracked	26.81 FL	*26.81 FL
5	1		*REAR BUMPER CENTRE LOWER GARNISH	Grazed	148.87 FL	*148.87 FL
6	1		*REAR BUMPER O/S REFLECTOR	Not Necessary	174.81 FL	*- FL
7	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	369.18 FL	*- FL
8	1		*O/S TAIL LAMP ASSY LED	Cracked	2,192.62 FL	*1,650.20 FL
9	2		*O/S TAIL LAMP CLIPS STOPPER	Not Necessary	11.42 FL	*- FL
10	1		*REAR O/S FENDER	Badly Dented / Buckled	1,242.88 FL	*1,242.88 FL
11	6		*REAR O/S FENDER INNER SHIELD CLIPS	Necessary	34.26 FL	*34.26 FL
12	1		*REAR O/S FENDER QUARTER GLASS SEAL	Necessary	36.71 FL	*36.71 FL
13	1		*REAR O/S FENDER QUARTER GLASS INNER DAMPER	Necessary	39.61 FL	*39.61 FL
14	1		*REAR O/S WHEEL GUARD GARNISH	Distorted	86.67 FL	*86.67 FL
15	10		*REAR O/S WHEEL GARNISH CLIPS & STOPPER	Not Necessary	57.10 FL	*- FL
16	1		*REAR O/S WHEEL GARNISH BRACKET	Twisted	37.17 FL	*37.17 FL
17	1		*REAR O/S SPORT RIM	Repair	821.71 FL	*- FL
18	1		*REAR O/S FENDER QUARTER GLASS SEALANT	Necessary	48.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,604.37	4,609.73
- List Item Discount on L Items 20.00/20.00% (S\$)	1,311.27	915.95
Total Parts (S\$)	5,293.10	3,693.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR O/S FENDER QUARTER GLASS & NECESSARY	New	150.00	60.00
3	TO REMOVE & REFIX CUSHION SEAT,CARPET,FLOOR MAT,GARNISH,FLOOR BOARD COVER,TOOL SET,SPARE TYRE & NECESSARY PARTS	New	180.00	80.00
4	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,350.00	600.00
6	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS,TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,250.00	800.00
Gross Labour Cost (\$\$)			3,130.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >