

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400292

INV Date : 16-08-2024

Reference CS3/SMR24080016/Rnp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. WC 4324B
Insured Veh. SHB 5448D
Claim No. TAX/07/24/2100
Policy No.
Accident Date 29/07/2024
Inspection Date 01/08/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref: Date: Code:	CS3/SMR24080016/Rnp3m4 16/08/2024 SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHB 5448D	Veh. Inspected	WC 4324B
	Policy No.	-	Coverage	0
	Claim No.	TAX/07/24/2100	Excess	\$0.00
	Assign From	HUA YEN	Assign Date	01/08/2024
2. Vehicle Details				
	Make & Model	SCANIA P340CB6X4MHZ	C.C	11705
	Engine No.	6665261	Year of Reg.	03/06/2011
	Chassis No.	XLEP6X40005262937	Colour	WHITE
	Odometer	443250 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	315/80R22.5	SUPER ETOT	8
	L/H Front Tyre	315/80R22.5	SUPER ETOT	8
	R/H Rear Tyre	315/80R22.5 (D)	SUPER ETOT	8/8
L/H Rear Tyre	315/80R22.5 (D)	SUPER ETOT	8/8	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
5. General Information				
	Accident Date	29/07/2024	Inspection Date	01/08/2024 (16:01)
	Survey held at	HSS ENVIRO PTE LTD - 24 TUAS AVENUE 2, SINGAPORE 639455		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B



PHOTOGRAPHS FOR VEHICLE NO. : WC 4324B

