

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080017/TPA3Q2
Date: 14/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : SNM4930E Insured Vehicle No : SLK5831K
Date of Loss: 27/07/2024 Nature of Claim: TP Claim No: MFL2024D0009884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNM4930E
Make & Model: HYUNDAI KONA, OS EV (A) Engine No: HIDDEN
Reg. Date: 27/09/2023 (Man. Year: 2023) Chassis No: KMHK281HUPU188409
Colour: Silver Odometer: 31824 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,852.00	1,199.00	4,653.00	79.51
Miscellaneous Items	208.08	208.08	0.00	0.00
Labour	3,050.00	1,370.00	1,680.00	55.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,110.08	2,777.08	6,333.00	69.52
+ GST 9.00/9.00% (S\$)	819.91	249.94	569.97	69.52
Nett Amount (S\$)	9,929.99	3,027.02	6,902.97	69.52
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,414.27		

INSPECTION

Date of Assignment: 01/08/2024 Present Location: Century Motors (Singapore) Pte Ltd (HQ)
Date Inspected: 01/08/2024 Inspected At: Century Motors (Singapore) Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days 6 Marsiling Lane,
Singapore 739145

Adjuster: MOHD TAUFIKH BIN HAMID Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	144	HYUNDAI KONA OS EV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNM4930E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	450.00 F	*450.00 F
2	1		*REAR BUMPER BRKT RH	Not Necessary	20.00 F	*- F
3	1		*REAR BUMPER BRKT LH	Not Necessary	20.00 F	*- F
4	1		*REAR BUMPER LOWER TRIM	Deformed	350.00 F	*350.00 F
5	1		*REAR BUMPER LOWER MOULDING	Not Necessary	70.00 F	*- F
6	1		*REAR BUMPER TOWING COVER	Not Necessary	10.00 F	*- F
7	1		*REAR BUMPER LIGHT LH	Not Necessary	300.00 F	*- F
8	1		*REAR BUMPER LIGHT RH	Not Necessary	300.00 F	*- F
9	1		*TAILGATE	Repair	800.00 F	*- F
10	1		*TAILGATE HINGE RH	Not Necessary	20.00 F	*- F
11	1		*TAILGATE HINGE LH	Not Necessary	20.00 F	*- F
12	1		*TAILGATE MOULDING	Deformed	60.00 F	*60.00 F
13	1		*NUMBER PLATE LIGHT LH	Not Necessary	40.00 F	*- F
14	1		*NUMBER PLATE LIGHT RH	Not Necessary	40.00 F	*- F
15	1		*REAR PARKING SENSOR	Not Working	150.00 F	*150.00 F
16	1		*TAILGATE LOCK	Not Necessary	150.00 F	*- F
17	1		*BOOT UPP TRIM COVER	Not Necessary	90.00 F	*- F
18	1		*TAIL LAMP RH	Not Necessary	300.00 F	*- F
19	1		*TAIL LAMP LH	Not Necessary	300.00 F	*- F
20	1		*BOOT LAMP RH	Not Necessary	300.00 F	*- F
21	1		*BOOT LAMP LH	Not Necessary	300.00 F	*- F
22	1		*REAR END PANEL	Repair	400.00 F	*- F
23	1		*REAR CAMERA	Not Necessary	700.00 F	*- F
24	1		*REAR BONNET HANDLE	Not Necessary	50.00 F	*- F
Supplementary #1						
25	1		*SKID PLATE PIECE LH	Cracked	35.00 F	*35.00 F
26	1		*SKID PLATE PIECE RH	Cracked	35.00 F	*35.00 F
27	1		*REAR BUMPER TOWING COVER	Deformed	10.00 F	*10.00 F

F=Franchise part.

Sub Total (S\$)	5,320.00	1,090.00
+ Margin on L,N Items 10.00/10.00% (S\$)	532.00	109.00
Total Parts (S\$)	5,852.00	1,199.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER CLIPS (NECESSARY)	35.00	35.00
2	1	REAR NUMBER PLATE & HOLDER (BENT)	40.00	40.00
3	1	REAR WINDSCREEN SEALANT (NECESSARY)	120.00	120.00
4	1	OD/TP Case (Insurer)	13.08	13.08
Sub Total (\$\$)			208.08	208.08

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	500.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,000.00	600.00
3	TO RESET PARKING SENSOR & ECU	New	250.00	150.00
4	TO REFIT REAR WINDSCREEN AND INNER TRIM COVER	New	250.00	120.00
5	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	150.00	0.00
Gross Labour Cost (\$\$)			3,050.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >