



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBC 7315G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT MUD GUARD	CRACKED	\$225.00	\$196.00
1	FRONT RIM	GRAZED/DENTED	\$300.00	\$300.00
1	FRONT RIM AXLE SHAFT	BENT	\$150.00	\$68.00
1	FRONT RIM BEARING LH }	WARPED	\$70.00	\$50.00
1	FRONT RIM BEARING RH }	WARPED	\$70.00	\$0.00
1	FRONT BRAKE DISC LH	NOT NECESSARY	\$300.00	\$0.00
1	FRONT BRAKE DISC RH	NOT NECESSARY	\$300.00	\$0.00
1	FRONT FORK LH	BENT	\$850.00	\$850.00
1	FRONT FORK RH	BENT	\$850.00	\$850.00
1	FRONT FORK LH OIL SEAL	NECESSARY	\$65.00	\$50.00
1	FRONT FORK RH OIL SEAL	NECESSARY	\$65.00	\$50.00
1	FRONT FORK UNDER BRACKET	BENT	\$350.00	\$350.00
1	CROWN HANDLE	BENT	\$200.00	\$200.00
1	STEERING TOP BEARING	WARPED	\$95.00	\$60.00
1	STEERING BOTTOM BEARING	WARPED	\$95.00	\$60.00
1	STEERING TOP BEAIRNG SEAL	NECESSARY	\$40.00	\$20.00
1	STEERING BOTTOM BEARING SEAL	NECESSARY	\$40.00	\$20.00
1	FRONT FOOT REST RH	GRAZED	\$95.00	\$95.00
1	FRONT FOOT REST BRACKET	GRAZED	\$110.00	\$110.00
1	REAR FOOT REST RH	GRAZED	\$95.00	\$95.00
1	BRAKE PEDAL	GRAZED	\$150.00	\$150.00
1	LH SIDE FAIRING	TO REPAIR SEE LABOUR	\$150.00	\$0.00
1	FUEL TANK	DENTED	\$850.00	\$850.00
1	METERING ASSY	CRACKED	\$750.00	\$750.00
1	SEAT ASSY	NOT NECESSARY	\$300.00	\$0.00
1	HANDLE BAR	BENT	\$260.00	\$260.00
1	HANDLE BAR GRIP LH	NOT NECESSARY	\$65.00	\$0.00
1	HANDLE BAR GRIP RH	DAMAGED	\$65.00	\$65.00
1	HANDLE BAR BALANCER LH	NOT NECESSARY	\$50.00	\$0.00
1	HANDLE BAR BALANCER RH	DAMAGED	\$50.00	\$50.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BRAKE LEVEL	GRAZED	\$85.00	\$85.00
1	HORN HIGH PITCH	DENTED	\$60.00	\$60.00
1	HORN LOW PITCH	DENTED	\$60.00	\$60.00
1	REAR TAIL FAIRING	TO REPAIR SEE LABOUR	\$580.00	\$0.00
1	REAR TAILLAMP	NOT NECESSARY	\$185.00	\$0.00
1	REAR HANDLE BAR	NOT NECESSARY	\$120.00	\$0.00
1	HEAD LAMP	CRACKED/DENTED	\$650.00	\$565.00
1	HEAD LAMP BRACKET	NOT NECESSARY	\$200.00	\$0.00
1	HEAD LAMP CHROME	CRACKED/DENTED	\$320.00	\$265.00
1	HEAD LAMP SIDE BRACKET LH	BENT	\$120.00	\$80.00
1	HEAD LAMP SIDE BRACKET RH	BENT	\$120.00	\$80.00
1	THROTTLE CABLE TOP	GRAZED	\$95.00	\$95.00
1	THROTTLE CABLE BOTTOM	NOT NECESSARY	\$95.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$974.50)	(\$683.90)
			<b>\$8,770.50</b>	<b>\$6,155.10</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT TYRE (SN)	SERVICEABLE	\$200.00	\$0.00
1	BLT FRONT FORK OIL (SN)	NECESSARY	\$150.00	\$60.00
1	REAR NUMBER PLATE (SN)	BENT	\$50.00	\$30.00
1	SET REAR EXHAUST PIPE (SN)	BUCKLED	\$2,000.00	\$1,400.00
1	SET REAR EXHAUST PIPE HEAD SHIELD END (SN)	SERVICEABLE	\$200.00	\$0.00
1	SET REAR EXHAUST PIPE GASKET (SN)	NECESSARY	\$200.00	\$60.00
1	SET REAR EXHAUST PIPE HOLDER (SN)	DEFORMED	\$150.00	\$80.00
1	LH SIDE CRASH BAR (SN)	BUCKLED	\$400.00	\$250.00
1	SET LH SIDE CRASH BAR TAPE (SN)	TORN	\$200.00	\$40.00
1	SET REAR SEAT CARBON FAIRING (SN)	NOT NECESSARY	\$500.00	\$0.00
2	FRONT SIDE MIRROR ASSY (SN)	CRACKED	\$200.00	\$150.00
1	FRONT VISION (SN)	GRAZED	\$300.00	\$200.00
1	SET HANDLE BAR SIDE GUARD (SN)	GRAZED	\$200.00	\$150.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR REFLECTOR (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$4,830.00	\$2,420.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TOWING		\$80.00	\$50.00
	WORKMANSHIP INCLUSIVE OF THE REPAIR OF LH SIDE FAIRING AND REAR TAIL FAIRING		\$800.00	\$300.00
	SPRAY PAINT		\$600.00	\$300.00
	TO CHECK THE WIRING SYSTEM TO FACILITATE THE REPAIR AND REFIT THE SAME		\$80.00	\$30.00
	REALIGN BODY FRAME		\$800.00	\$200.00
	TO CONDUCT WHEEL ALIGNMENT		\$100.00	\$20.00
	TO CONDUCT WHEEL BALANCING TO FACILITATE THE REPAIR		\$80.00	\$20.00
	TO REMOVE, RENEW AND REFIT TYRE TO FACILITATE THE		\$80.00	\$20.00
	TO REMOVE AND REFIT ALL FITTINGS TO THE FUEL TANK ASSY TO FACILITATE THE REPAIR		\$100.00	\$50.00
	TO R&R REAR EXHAUST PIPE ASSY		\$100.00	\$50.00
	TO CONDUCT FORK ALIGNMENT		\$300.00	\$50.00
			\$3,120.00	\$1,090.00
<b>GRAND TOTAL</b>			<b>\$16,720.50</b>	<b>\$9,665.10</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$7,700.00</b>
Report Ref No: CS1/LAW24080018/Eqh3m4				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.