

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080020/UMA3Q2**Date:** 05/05/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070150026
Claimant Vehicle No :	GBA5793H	Insured Vehicle No :	GBG8637A
Date of Loss:	31/07/2024	Nature of Claim:	TP
		Claim No:	9102258520SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA5793H	Engine No:	1KD1683881
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y403001329
Reg. Date:	04/09/2007 (Man. Year: 2007)	Odometer:	473764 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,262.30	1,669.30	6,593.00	79.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,120.00	1,460.00	56.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,842.30	2,789.30	8,053.00	74.27
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	10,842.30	2,200.00	8,642.30	79.71
+ GST 9.00/9.00% (S\$)	975.81	198.00	777.81	79.71
Nett Amount (S\$)	11,818.11	2,398.00	9,420.11	79.71
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,725.25		
Global Sum Settlement (S\$)		2,700.00		

INSPECTION

Date of Assignment:	02/08/2024	
Date Inspected:	02/08/2024	Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ) 1 KAKI BUKIT AVENUE 6 #01-73 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR GARNISH LH	Cracked	341.30 FL	*341.30 FL
2	1		*FRONT SIDE MIRROR BRACKET LH	Not Necessary	145.70 FL	*- FL
3	1		*FRONT SIDE MIRROR LH	Not Necessary	322.60 FL	*- FL
4	1		*FRONT CENTRE BLACK GARNISH LH	Cracked	187.20 FL	*187.20 FL
5	1		*FRONT CORNER PANEL LH	Dented	396.10 FL	*396.10 FL
6	1		*FRONT GRILLE	Not Necessary	809.10 FL	*- FL
7	1		*FRONT GRILLE LOGO	Not Necessary	70.80 FL	*- FL
8	1		*FRONT CENTRE PANEL	Repair	1,619.90 FL	*- FL
9	1		*HEADLAMP LH	Cracked	1,247.80 FL	*1,247.80 FL
10	1		*FRONT BUMPER	Repair	748.90 FL	*- FL
11	1		*FRONT BUMPER BRACKET LH	Not Necessary	160.00 FL	*- FL
12	1		*AIRCON CONDENSOR LH	Not Necessary	1,827.00 FL	*- FL
13	1		*FRONT DOOR ASSY LH	Repair	1,784.70 FL	*- FL
14	1		*FRONT DOOR WINDOW GLASS MOULDING LH	Not Necessary	211.20 FL	*- FL
15	2		*FRONT DOOR HINGES LH	Not Necessary	158.00 FL	*- FL
16	1		*FRONT DOOR CHECKER LH	Not Necessary	65.00 FL	*- FL
17	1		*FRONT STEP GARNISH LH	Not Necessary	321.10 FL	*- FL
18	1		*FRONT CENTRE BLACK GARNISH LH CLIPS	Not Necessary	40.00 FS	*- FS
19	1		*FRONT CORNER PANEL LH CLIPS	Not Necessary	40.00 FS	*- FS
20	1		*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
21	1		*FRONT DOOR TRIMBOARD LH	Not Necessary	60.00 FS	*- FS
22	1		*FRONT DOOR COMPANY STICKER LH	Necessary	70.00 FS	*40.00 FS
23	1		*SET FRONT DOOR WINDOW VISOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,866.40	2,212.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,604.10	543.10
Total Parts (\$\$)	8,262.30	1,669.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT WIRING & HEADLAMP LEVELING	New	60.00	20.00
2	TO REPLACE CONDENSER LH AND RECHARGE AC GAS	New	160.00	0.00
3	TO REMOVE AND TRANSFER FRONT LH DOOR FITTINGS	New	120.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
5	TO PROVIDE LABOUR WORKMANSHIP	New	1,000.00	500.00
6	TO SPRAY PAINT ON AFFECTED PANELS	New	1,000.00	600.00
7	RUST PROOFING	New	120.00	0.00
Gross Labour Cost (\$\$)			2,580.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >