



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBE 309K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BENT	\$727.10	\$727.10
2	HEAD LAMP @\$997.30	N/S CRACKED	\$1,994.60	\$997.30
2	HEAD LAMP LOWER RUBBER @\$47.20	NOT NECESSARY	\$94.40	\$0.00
1	FRONT GRILLE	CRACKED	\$479.80	\$479.80
1	FRONT GRILLE LOGO	NECESSARY	\$78.00	\$78.00
1	FRONT PANEL	DENTED	\$1,156.70	\$1,156.70
1	FRONT PANEL EMBLEM 'DYNA'	NECESSARY	\$78.60	\$78.60
1	FRONT WIPER PANEL	DENTED	\$349.60	\$349.60
1	FRONT WIPER HEAD C/W LINKAGE	NOT NECESSARY	\$424.10	\$0.00
1	FRONT CHASSIS CROSS MEMBER	DENTED	\$789.50	\$789.50
1	FRONT TOW HOOK	NOT NECESSARY	\$285.00	\$0.00
1	FRONT WINDSCREEN PRIMER	NECESSARY	\$365.00	\$365.00
1	FRONT CABIN HINGE	NOT NECESSARY	\$3,270.00	\$0.00
1	FRONT APRON GARNISH (CENTER)	CUT	\$296.70	\$296.70
2	FRONT CORNER PANEL LOWER APRON GARNISH @\$114.90	N/S CUT	\$229.80	\$114.90
2	FRONT CORNER PANEL (UPPER) @\$196.80	NOT NECESSARY	\$393.60	\$0.00
2	FRONT CORNER PANEL (LOWER) @\$247.70	NOT NECESSARY	\$495.40	\$0.00
1	FRONT DOOR PILLAR LH	TO REPAIR SEE LABOUR	\$1,490.00	\$0.00
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	\$1,685.00	\$0.00
2	FRONT DOOR HINGE LH @\$98.00	NOT NECESSARY	\$196.00	\$0.00
1	FRONT DOOR STEP PANEL LH	CUT	\$132.00	\$132.00
1	AIR CON BLOWER MOTOR	CRACKED	\$1,394.00	\$1,394.00
1	AIR CON COOLING COIL	CRACKED	\$2,439.00	\$1,350.00
2	AIR CON PIPE @\$475.00	NOT NECESSARY	\$950.00	\$0.00
1	AIR CON CONDENSER	NOT NECESSARY	\$826.80	\$0.00
1	AIR CON FAN COWLING C/W MOTOR	NOT NECESSARY	\$498.90	\$0.00
1	AIR CON CONDENSER BRACKET	NOT NECESSARY	\$246.70	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$5,341.58)	(\$2,077.30)
			\$16,024.72	\$6,231.90



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	DENTED	\$50.00	\$30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	\$40.00	\$30.00
1	FRONT PANEL SEALANT (SN)	NECESSARY	\$150.00	\$60.00
1	FRONT DOOR SEALANT LH (SN)	NOT NECESSARY	\$150.00	\$0.00
1	SET FRONT DOOR LTA STICKER (SN)	NECESSARY	\$60.00	\$30.00
1	SET DASHBOARD CLIP (SN)	NOT NECESSARY	\$150.00	\$0.00
1	SET DASHBOARD CENTER GARNISH CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NECESSARY	\$80.00	\$40.00
1	FRONT WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	\$60.00	\$30.00
1	FRONT ERP BRACKET (SN)	NOT NECESSARY	\$40.00	\$0.00
1	DOOR VISOR (SN)	NOT NECESSARY	\$180.00	\$0.00
			\$1,010.00	\$220.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK. INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR LH AND FRONT DOOR LH		\$2,000.00	\$800.00
	TO PUTTY, SPRAY PAINT, POLISH WAX		\$1,800.00	\$800.00
	TO SPRAY TUFF COAT		\$250.00	\$60.00
	WIRING, BULB CHECKING		\$80.00	\$30.00
	CONDUCT WATER TER LEAKAGE TEST	NOT NECESSARY	\$80.00	\$0.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	NOT NECESSARY	\$250.00	\$0.00
	REFOCUS HEADLAMP BEAM	NOT NECESSARY	\$60.00	\$0.00
	REMOVE AND REFIX DOOR WINDOW GLASS	NOT NECESSARY	\$80.00	\$0.00
	TRANSFER FRONT DOOR MECHANISM	NOT NECESSARY	\$80.00	\$0.00
	REMOVE AND REFIX AIRCON BLOWER, COOLING COIL, AIR CON CONDENSER AND REFILL AIRCON GAS	NOT NECESSARY	\$250.00	\$0.00
	REMOVE AND REINSTALL DASHBOARD	NOT NECESSARY	\$650.00	\$0.00
	REMOVE AND REFIX FRONT WINDSCREEN		\$120.00	\$120.00
	REMOVE AND REFIX FRONT VIDEO RECORDER	NOT NECESSARY	\$80.00	\$0.00
	RESET RADIO SYSTEM	NOT NECESSARY	\$200.00	\$0.00
	LIFT UP CABIN	NOT NECESSARY	\$1,800.00	\$0.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC		\$180.00	\$0.00
			\$7,960.00	\$1,810.00
<b>GRAND TOTAL</b>			<b>\$24,994.72</b>	<b>\$8,261.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$6,600.00</b>
<b>Report Ref No: CS/TP24080022/Avh3e2</b>				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.