



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO RU 5008Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BROKEN	\$398.25	\$398.25
1	LHR RETAINER	BROKEN	\$60.75	\$60.75
1	END DOOR	DENTED	\$1,147.50	\$1,147.50
1	LHR LAMP ASSY	BROKEN	\$297.00	\$297.00
1	BOTH DOOR WEATHERSTRIPS	NECESSARY	\$405.00	\$405.00
			\$2,308.50	\$2,308.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE REAR END DOOR, GLASS, REPAIR END PANEL & END FLOOR PANEL, REAR LH FENDER, PANEL, BUMPER & WEATHERSTRIP		\$3,240.00	\$1,800.00
	RESPRAY REAR END DOOR, END PANEL, LHR FENDER, PANEL & BUMPER		\$1,309.50	\$1,000.00
	REPLACE & RESEAL NUMBER PLATE		\$337.50	\$100.00
	TOWING CHARGES (2 WAYS)		\$324.00	\$150.00
			\$5,211.00	\$3,050.00

GRAND TOTAL		\$7,519.50	\$5,358.50
	RECOMMENDED COST OF REPAIRS		\$5,358.50
Report Ref No: CS/LAW24080025/Evp3e2			

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.