

**Description of Parts** 

AND REPLACEMENT OF DAMAGES

LABOUR CHARGES FOR REMOVE / REFIT, CUTTING / WELDING

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJV 2598U

	Nett								
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)					
1	REAR BUMPER (N)	BUCKLED	\$617.20	\$617.20					
1	REAR BUMPER LOWER BLACK SPOILER (N)	DISTORTED	\$112.60	\$112.60					
2	REAR BUMPER REVERSE SENSOR (N)	CUT	\$519.00	\$519.00					
2	REAR BUMPER SIDE RETAINER (N)	SERVICEABLE	\$39.00	\$0.00					
1	REAR BUMPER INNER REINFORCEMENT (N)	BENT	\$295.50	\$295.50					
1	SET REAR BUMPER CLIPS (N)	NECESSARY	\$40.00	\$40.00					
2	TAILLAMP (N)	CUT	\$633.00	\$633.00					
1	REAR BOOT LID (N)	BENT	\$760.00	\$760.00					
2	REAR BOOT SIDE LAMP (N)	O/S CUT	\$337.00	\$168.50					
1	REAR BOOT OUTER COVER/GARNISH (N)	MTG DISTORTED	\$121.80	\$121.80					
1	REAR BOOT CENTRE 'H' LOGO (N)	NECESSARY	\$19.80	\$19.80					
1	REAR BOOT LH 'CIVIC' EMBLEM (N)	NECESSARY	\$24.50	\$24.50					
1	REAR BOOT RH 'I-VTEC' EMBLEM (N)	NECESSARY	\$30.80	\$30.80					
1	REAR BOOT REVERSE CAMERA (N)	CUT	\$385.00	\$385.00					
1	REAR BOOT TOP LOCK (N)	DENTED	\$145.00	\$145.00					
1	SET REAR BOOT INNER TRIM CLIPS (N)	NECESSARY	\$50.00	\$50.00					
1	REAR END PANEL (N)	BENT	\$395.00	\$395.00					
1	ANTENNA SENSOR (N) (ADDITIONAL)	CRACKED	\$164.70	\$164.70					
1	REAR END PANEL TOP GARNISH (N) (ADDITIONAL)	MTG DISTORTED	\$58.50	\$58.50					
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$908.18)					
			\$4,748.40	\$3,632.72					
	Special	Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)					
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	\$60.00	\$30.00					
1	REAR NUMBER PLATE (SN)	SERVICEABLE	\$50.00	\$0.00					
		\$110.00	\$30.00						
Labour									

Pag	e	1	of	2
ı au	·		OI.	_

Condition

Workshop Estimate (\$)

\$800.00

Our Adjusted (\$)

\$600.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
TO PUTTY AND SPRAY PAINTINGS CHARGES		\$1,000.00	\$700.00		
TO REMOVE, REFIT REAR BOOT LID FITTINGS		\$80.00	\$50.00		
TO REMOVE, REFIT REVERSES SENSORS & REVERSE CAMERA		\$120.00	\$80.00		
TO REMOVE, REFIT REAR UPHOLSTERY & ATTACHMENTS		\$120.00	\$50.00		
TO SUPPLY AND APPLY ANTI RUST TREATMENT		\$80.00	\$60.00		
		\$2,200.00	\$1,540.00		
GRAND TOTAL		\$7,058.40	\$5,202.72		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,150.00		
Report Ref No: CS/TP24080027/Kvh3e2					

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.