

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24080031/AMA3Q2**Date:** 05/03/2025**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800024660   |
| <b>Claimant Vehicle No :</b> | SNA6513B                             | <b>Insured Vehicle No :</b> | SLW9852K     |
| Date of Loss:                | 21/07/2024                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3584760557SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SNA6513B</b>                   |             |              |
| Make & Model:               | TOYOTA NOAH HYBRID, 1.8 X CVT (A) | Engine No:  | 2ZR2L92962   |
| Reg. Date:                  | 01/07/2021 (Man. Year: 2021)      | Chassis No: | ZWR800493936 |
| Colour:                     | Black                             | Odometer:   | 174436 km    |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/60 R15    | Rear Tyre Size:  | 195/60 R15    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 7,682.40          | 3,495.82          | 4,186.58          | 54.50         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 3,210.00          | 660.00            | 2,550.00          | 79.44         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>10,892.40</b>  | <b>4,155.82</b>   | <b>6,736.58</b>   | <b>61.85</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>3,300.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 10,892.40         | 3,300.00          | 7,592.40          | 69.70         |
| <b>+ GST 9.00/9.00% (S\$)</b>                    | 980.32            | 297.00            | 683.32            | 69.70         |
| <b>Nett Amount (S\$)</b>                         | <b>11,872.72</b>  | <b>3,597.00</b>   | <b>8,275.72</b>   | <b>69.70</b>  |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                   | 400.00            |                   |               |
| <b>(S\$)</b>                                     |                   | 3,997.00          |                   |               |
| <b>Liabe Amount (50.00%) (S\$)</b>               |                   | <b>1,998.50</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>1,950.00</b>   |                   |               |

**INSPECTION**

|                             |            |               |                                                                           |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------|
| Date of Assignment:         | 30/07/2024 |               |                                                                           |
| Date Inspected:             | 30/07/2024 | Inspected At: | Xin Hua Workshop Pte Ltd<br>8 KAKI BUKIT AVE 4 #04-07<br>Singapore 415875 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                           |

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BONNET                                    | Not Necessary | 910.80 FL   | *- FL        |
| 2   | 1   |          | *BONNET HINGES                             | Not Necessary | 85.60 FL    | *- FL        |
| 3   | 1   |          | *FRONT BUMPER                              | Torn          | 1,265.80 FL | *1,265.80 FL |
| 4   | 1   |          | *FRONT BUMPER UNDERCOVER                   | Not Necessary | 198.50 FL   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER LOWER AIR GUARD              | Not Necessary | 145.30 FL   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER FOG LAMP COVER RH            | Not Necessary | 89.60 FL    | *- FL        |
| 7   | 1   |          | *FRONT BUMPER SIDE RETAINER RH             | Not Necessary | 93.60 FL    | *- FL        |
| 8   | 1   |          | *HEADLAMP (LED) RH                         | Cracked       | 3,355.30 FL | *3,355.30 FL |
| 9   | 1   |          | *HEADLAMP OUTER GARNISH                    | Not Necessary | 83.50 FL    | *- FL        |
| 10  | 1   |          | *FRONT WASHER TANK                         | Not Necessary | 165.90 FL   | *- FL        |
| 11  | 1   |          | *FRONT WASHER TANK MOTOR                   | Not Necessary | 236.80 FL   | *- FL        |
| 12  | 1   |          | *FRONT GRILLE (COMPLETE SET)               | Not Necessary | 1,148.50 FL | *- FL        |
| 13  | 1   |          | *FRONT FENDER RH                           | Repair        | 758.90 FL   | *- FL        |
| 14  | 1   |          | *FRONT FENDER INNER COWLING RH             | Not Necessary | 245.80 FL   | *- FL        |
| 15  | 1   |          | *FRONT WHEEL RIM RH                        | Not Necessary | 1,219.30 FL | *- FL        |
| 16  | 1   |          | *FRONT NUMBER PLATE                        | Not Necessary | 50.00 FS    | *- FS        |
| 17  | 1   |          | *SET FRONT BUMPER CLIP                     | Necessary     | 40.00 FS    | *30.00 FS    |
| 18  | 1   |          | *SET FRONT BUMPER LOWER GRILLE CLIP        | Not Necessary | 30.00 FS    | *- FS        |
| 19  | 1   |          | *SET FRONT BUMPER UNDER COVER GARNISH CLIP | Not Necessary | 30.00 FS    | *- FS        |
| 20  | 1   |          | *SET FRONT FENDER COWLING CLIPS            | Not Necessary | 30.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>10,183.20</b> | <b>4,651.10</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 2,500.80         | 1,155.28        |
| <b>Total Parts (\$)</b>                                  | <b>7,682.40</b>  | <b>3,495.82</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--------------------------------------------|----------|-----------------|---------------|
| <b>Labour Items</b>             |                                            |          |                 |               |
| 1                               | PANEL BEATING REMOVING AND REPLACING PARTS | New      | 1,400.00        | 200.00        |
| 2                               | SPRAY PAINTING TO AFFECTED AREA            | New      | 1,400.00        | 400.00        |
| 3                               | TUFF COAT                                  | New      | 250.00          | 30.00         |
| 4                               | WIRING CHECK                               | New      | 100.00          | 30.00         |
| 5                               | REFOCUS HEADLAMP BEAM                      | New      | 60.00           | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                            |          | <b>3,210.00</b> | <b>660.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >