



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080036/Eqp3
16 RAFFLES QUAY	Date:	16/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6617B	Veh. Inspected	SME 2325U
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006680MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	02/08/2024

2. Vehicle Details

Make & Model	HONDA GRACE HYBRID	C.C	1496
Engine No.	LEB6441718	Year of Reg.	24/09/2018
Chassis No.	GM41201713	Colour	BLACK
Odometer	76548 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R16	TOURADOR	5
L/H Front Tyre	195/55 R16	TOURADOR	5
R/H Rear Tyre	195/55 R16	TOURADOR	5
L/H Rear Tyre	195/55 R16	TOURADOR	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2024	Inspection Date	02/08/2024
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days