



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|--|-------|-----------------------|
| MS AUTO & GENERAL INSURANCE (S) PL | Ref: | CS/AGI24080039/Kqp3e2 |
| (BUDGET DIRECT INSURANCE) | Date: | 05/11/2024 |
| 190 CLEMENCEAU AVENUE #03-01 | Code: | AGI |
| SINGAPORE SHOPPING CENTRE SINGAPORE 239924 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | SNB 648E | Veh. Inspected | SNC 5605R |
| Policy No. | P10779920R01 | Coverage | 0 |
| Claim No. | C10030713/CY | Excess | \$0.00 |
| Assign From | CALEEN YIT | Assign Date | 02/08/2024 |

2. Vehicle Details

| | | | |
|-----------------|--------------------------|--------------|----------------|
| Make & Model | MERCEDES BENZ A180 (A) | C.C | 1332 |
| Engine No. | 28291480677039 | Year of Reg. | 28/10/2021 |
| Chassis No. | W1K1770842J324756 | Colour | METALLIC BLACK |
| Odometer | 100855 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: STANDARD ALLOY RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|------------|----------|--------------|
| R/H Front Tyre | 225/45 R16 | MICHELIN | 8 |
| L/H Front Tyre | 225/45 R16 | MICHELIN | 8 |
| R/H Rear Tyre | 225/45 R16 | MICHELIN | 8 |
| L/H Rear Tyre | 225/45 R16 | MICHELIN | 8 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 24/07/2024 | Inspection Date | 05/08/2024 |
| Survey held at | TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days