

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3148/06/24 Your Ref: Date: 20th June 2024



The Claim's Manager
Motor Claims Dept.
INDIA INTERNATIONAL INSURANCE PTE. LTD.
6, Raffles Quay, #22-00
Singapore 048580

Name Of Insured : Mr Tan Teck Sin
Date Of Accident : 12/06/24 (12:40hrs)
Policy Number : D19MPC0001416_05

Cost of repair to TOYOTA SIENTA 1.5 (A) S/Wagon - SBE 2323 E

To supply front bumper, clips, retainer, centre grille base,
fog lamp assy, garnish, n/s head lamp assy, front n/s fender,
inner shield, clips, n/s side mirror comp, n/s head lamp panel
& necessary parts.

Labour charge to remove & cut out damaged parts, to jack,
straighten & knocking out front n/s door, front support panel
& necessary parts.

To putty & respray painting on all affected accident parts,
including wiring check up & adjust headlight alignment.

Lump Sum Repair	:	\$ 4,700.00
Less Owner Excess	:	\$ 600.00
Balance	:	\$ 4,100.00
		=====

Dollars : Four Thousand And One Hundred Only.

HUP MOTOR TRADING & SERVICE


.....

Encl : Discharge Voucher,