10/11/24, 2:48 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080041/UUA3Q2

Date: 11/10/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0009135_01

Claimant Vehicle SNN4226A Insured Vehicle No: SJA1125T

No:

Date of Loss: 02/08/2024 Nature of Claim: TP Claim No: MPC2024D0010282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNN4226A

Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25500121

Reg. Date: 23/03/2018 (Man. Year: 2018) Chassis No: MRHFC5650JT000084

Colour: Black Odometer: 123243 km

Engine Capacity: 1597 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: **Engine Modification:** No Handbrake (Serviceable): Yes

CONDITION OF TYRES

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18 Front Left Side: Rear Left Side: Grenlander 6 mm Grenlander 6 mm Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|----------------------|------------|------------|--------|
| Parts | 5,395.76 | 2,208.40 | 3,187.36 | 59.07 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,880.00 | 920.00 | 1,960.00 | 68.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,275.76 | 3,128.40 | 5,147.36 | 62.20 |
| Approved Total (Overridden) (S\$) | | 2,500.00 | | |
| Nett Amount (S\$) | 8,275.76 | 2,500.00 | 5,775.76 | 69.79 |
| + Car Rental (3.0 x S | \$120.00/day) (S\$) | 360.00 | | |
| + Doo | c/Search Fee (S\$) | 33.18 | | |
| | Nett Liability (S\$) | 2,893.18 | | |

INSPECTION

Date of Assignment: 06/08/2024

Zoom Autowerks Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-53 Date Inspected: 06/08/2024 Inspected At:

Singapore 417808

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2024)

Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNN4226A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------------|--------------|--------------|---|-------------------|-------------|--------------|
| 1 | 1 | | *FRONT HEADLAMP RH | Not Necessary | 1,700.60 FL | *-FL |
| 2 | 1 | | *FRONT HEADLAMP TOP MOULDING | Not Necessary | 227.50 FL | *- FL |
| 3 | 1 | | *FRONT HEADLAMP LOWER BRACKET | Not Necessary | 97.60 FL | *- FL |
| 4 | 1 | | *FRONT GRILLE BASE | Not Necessary | 188.50 FL | *- FL |
| 5 | 1 | | *FRONT GRILLE LOGO | Not Necessary | 79.50 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER BRACKET | Not Necessary | 68.50 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER SIDE RETAINERS | Not Necessary | 85.20 FL | *- FL |
| 8 | 1 | | *FRONT BUMPER TOP BEAM | Not Necessary | 200.30 FL | *- FL |
| 9 | 1 | | *FRONT FENDER RH | Repair | 386.90 FL | *- FL |
| 10 | 1 | | *FRONT FENDER INNER SHIELD | Not Necessary | 149.60 FL | *- FL |
| 11 | 1 | | *FRONT FENDER SIGNAL LAMP (O/S) | Scratched | 85.50 FL | *85.50 FL |
| 12 | 1 | | *FRONT BUMPER ASSY | Cut / Torn | 1,800.00 FS | *1,300.00 FS |
| 13 | 1 | | *FRONT BUMPER LOWER SPOILER | Cut | 850.00 FS | *800.00 FS |
| 14 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 80.00 FS | *40.00 FS |
| 15 F=Fra | 1 inchise | part. S=SpcN | *SET FRONT FENDER INNER SHIELD CLIP lett. L=ListItemDisc. | Not Necessary | 50.00 FS | *- FS |
| | | | | Sub Total (S\$) | 6,049.70 | 2,225.50 |
| | | | - List Item Discount on L | • • • | 653.94 | 17.10 |
| | | | | Total Parts (S\$) | 5,395.76 | 2,208.40 |
| | | | Report was unsubmitted durin | g this print-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|----------------------------|------------|--------|
| Lab | our Items | | | |
| 1 | TO CHECK WIRING AND RESET HEADLAMP FOCUSING | New | 80.00 | 20.00 |
| 2 | TO APPLY UNDERCOATING | New | 100.00 | 0.00 |
| 3 | PANEL BEATING | New | 1,400.00 | 300.00 |
| 4 | TO RESPRAY PAINTING ON THE AFFECTED AREAS | New | 1,300.00 | 600.00 |
| | | Gross Labour Cost (S\$) | 2,880.00 | 920.00 |
| | Report was unsubmit | ted during this print-out. | | |

< END OF ESTIMATES >