

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080048/DMA3Q2
Date: 17/03/2025

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_04
Claimant Vehicle No :	SHA2729T	Insured Vehicle No :	YQ6176B
Date of Loss:	03/08/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0009951

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2729T	Engine No:	G4LEKU401751
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU187941
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	614490 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,438.08	14,477.24	18,960.84	56.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,040.00	1,840.00	4,200.00	69.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,478.08	16,317.24	23,160.84	58.67
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	39,478.08	13,000.00	26,478.08	67.07
+ GST 9.00/9.00% (S\$)	3,553.03	1,170.00	2,383.03	67.07
Nett Amount (S\$)	43,031.11	14,170.00	28,861.11	67.07
+ Car Rental (13.0 x S\$114.78/day) (S\$)		1,492.14		
+ Loss of Earnings (13.0 x S\$40.00/day) (S\$)		520.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		16,289.39		
Global Sum Settlement (S\$)		16,200.00		

INSPECTION

Date of Assignment:	06/08/2024		
Date Inspected:	06/08/2024	Inspected At:	BIFROST AUTO PTE LTD - LOYANG (HQ) 59 Loyang Drive Level 4 Room 7 Singapore 508969
Estimated Period of Repair:	11.0 days		

Adjuster: BRYAN TANI

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2025)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2729T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,253.80 FL	*2,253.80 FL
2	1		*BONNET HINGE (LH/RH)	O/S Repair / N/S Bent	237.40 FL	*118.70 FL
3	1		*BONNET MOULDING	Not Necessary	41.40 FL	*- FL
4	1		*BONNET LOCK	Repair	127.30 FL	*- FL
5	1		*BONNET INSULATOR	Not Necessary	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*RADIATOR GRILLE NEW MODEL	Not Necessary	1,568.60 FL	*- FL
8	1		*FLAP ASSY ACTIVE AIR UPPER (LH)	Not Necessary	824.60 FL	*- FL
9	1		*FRONT BUMPER COVER	Broken	481.10 FL	*481.10 FL
10	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Not Necessary	186.90 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,136.70 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT ABSORBER (LH)	Not Necessary	186.50 FL	*- FL
14	1		*FRONT BUMPER TOWING COVER	Not Necessary	29.00 FL	*- FL
15	1		*FRONT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
16	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
17	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	365.30 FL	*- FL
19	1		*FRONT BUMPER LOWER GRILLE MOULDING	Not Necessary	127.60 FL	*- FL
20	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
21	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	35.00 FL	*- FL
22	1		*FRONT BUMPER BRACKET (LH)	Broken	28.00 FL	*28.00 FL
23	1		*FRONT BUMPER RETAINER MOUNTING (LH)	Not Necessary	65.30 FL	*- FL
24	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
25	1		*FRONT GRILLE (LH)	Dislodged	186.90 FL	*186.90 FL
26	1		*FRONT BUMPER AIR DUCT (LH)	Dislodged	153.80 FL	*153.80 FL
27	1		*DAY LIGHT LH	Mtg Broken	642.50 FL	*642.50 FL
28	1		*BUZZER ASSY -PIEZO (LH)	Not Necessary	388.00 FL	*- FL
29	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,139.30 FL	*1,139.30 FL
30	1		*HEADLAMP (LH)	Broken	3,987.30 FL	*3,987.30 FL
31	1		*HORN UNIT (LH)	Not Necessary	72.80 FL	*- FL
32	1		*RADIATOR INVERTER	Not Necessary	884.80 FL	*- FL
33	1		*RADIATOR	Not Necessary	710.50 FL	*- FL
34	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,459.60 FL	*- FL
35	1		*RADIATOR AIR GUARD (LH)	Not Necessary	76.40 FL	*- FL
36	1		*RADIATOR AIR GUARD UPR (LH)	Not Necessary	127.50 FL	*- FL
37	1		*FRT PILLAR UPPER COVER OUTER (LH)	Dislodged	89.60 FL	*89.60 FL
38	1		*FRONT FENDER (LH)	Buckled	490.70 FL	*490.70 FL
39	1		*FRONT FENDER APRON PANEL (LH)	Buckled	756.20 FL	*756.20 FL
40	1		*FRONT FENDER APRON PANEL UPPER (LH)	Buckled	329.00 FL	*329.00 FL
41	1		*FRONT FENDER SHIELD (LH)	Torn	164.70 FL	*164.70 FL
42	1		*AIRCON CONDENSER	Not Necessary	663.60 FL	*- FL
43	1		*FRONT WINDSCREEN GLASS	Not Necessary	1,558.10 FL	*- FL
44	1		*FRONT WINDSCREEN MOULDING	Not Necessary	157.30 FL	*- FL
45	1		*WIPER TOP GARNISH	Not Necessary	681.20 FL	*- FL
46	1		*WIPER TOP GARNISH SIDE COVER (LH)	Not Necessary	86.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LH FUSE BOX HARNESS	Broken	6,854.85 FL	*6,854.85 FL
48	1		*FRONT WHEEL RIM (LH)	Not Necessary	1,124.20 FL	*- FL
49	1		*FRONT WHEEL HUB ASSY (LH)	Not Necessary	678.50 FL	*- FL
50	1		*FRONT WHEEL HUB CAP	Not Necessary	346.40 FL	*- FL
51	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Not Necessary	372.50 FL	*- FL
52	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	372.50 FL	*- FL
53	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,136.70 FL	*- FL
54	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
55	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
56	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
57	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
58	1		*FRONT SUSPENSION LOWER ARM (LH)	Not Necessary	596.80 FL	*- FL
59	1		*KNUCKLE ARM (LH)	Not Necessary	663.60 FL	*- FL
60	1		*ENGINE UNDER COVER	Not Necessary	469.40 FL	*- FL
61	1		*ENGINE CROSSMEMBER	Not Necessary	1,803.90 FL	*- FL
62	1		*COOLANT	Not Necessary	45.00 FS	*- FS
63	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	26.60 FL	*26.60 FL
64	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
65	1		*FRONT ERP STICKER	Not Necessary	30.00 FS	*- FS
66	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	41,713.35	18,096.55
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,275.27	3,619.31
Total Parts (\$\$)	33,438.08	14,477.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,800.00	800.00
3	WIRING CHARGE	New	100.00	20.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	REMOVE/REFIX RADIATOR	New	90.00	0.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
10	REMOVE/REFIX FUSE BOX	New	350.00	200.00
11	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			6,040.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >