



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060088/Uqh3
16 RAFFLES QUAY	Date:	13/06/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3171J	Veh. Inspected	SLB 7997A
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24004940MFCT	Excess	\$0.00
Assign From	HARMINDER KAUR	Assign Date	13/06/2024

### 2. Vehicle Details

Make & Model	TOYOTA VELLFIRE (A)	C.C	2493
Engine No.	2ARH661615	Year of Reg.	22/04/2016
Chassis No.	AGH300049561	Colour	BLACK
Odometer	201585 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55R18	PIRELLI	6
L/H Front Tyre	235/55R18	PIRELLI	6
R/H Rear Tyre	235/55R18	TOYO	6
L/H Rear Tyre	235/55R18	TOYO	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/06/2024	Inspection Date	14/06/2024
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days