

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080051/UVP3E2
Date: 21/08/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003108909
Claimant Vehicle No :	SMD470B	Insured Vehicle No :	SMK9209U
Date of Loss:	28/07/2024	Nature of Claim:	TP
		Claim No:	368736

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD470B		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 SB URBAN (R18 LED) (A)	Engine No:	27091031661511
Reg. Date:	31/07/2018 (Man. Year: 2018)	Chassis No:	WDD1179422N677067
Colour:	White	Odometer:	142547 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,154.32	5,026.86	15,127.46	75.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	980.00	1,380.00	58.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,514.32	6,006.86	16,507.46	73.32
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	22,514.32	4,800.00	17,714.32	78.68

INSPECTION

Date of Assignment:	05/08/2024	
Date Inspected:	05/08/2024	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2024)
Parts:	143	MERCEDES-BENZ CLA180 1.6 SB URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD470B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	2,200.00 FN	*1,785.32 FN
2	2		*FRONT BUMPER BRACKETS - L-R	Not Necessary	170.00 FN	*- FN
3	1		*FRONT BUMPER DISTANCE SENSOR L-R OUTER (2PCS)	Malfunction (1Pc Only)	394.40 FN	*197.20 FN
4	2		*FRONT BUMPER DISTANCE SENSOR L-R - INNER	Serviceable	394.40 FN	*- FN
5	1		*FRONT BUMPER SPONGE	Torn	125.00 FN	*125.00 FN
6	1		*FRONT BUMPER MOULDING	Scratched	278.00 FN	*166.80 FN
7	1		*FRONT GRILLE	Not Necessary	600.00 FN	*- FN
8	1		*FRONT HEADLAMP L-R	N/S Cracked	9,600.00 FN	*3,255.53 FN
9	2		*FRONT HEADLAMP LOWER BRACKET L-R	Not Necessary	170.00 FN	*- FN
10	2		*FRONT HEADLAMP TOP BRACKET L-R	Not Necessary	170.00 FN	*- FN
11	1		*BONNET	Repair	2,300.00 FN	*- FN
12	1		*BONNET CENTRE LOCK	Not Necessary	185.00 FN	*- FN
13	1		*BONNET LOCK	Not Necessary	250.80 FN	*- FN
14	2		*BONNET HINGE	Not Necessary	217.20 FN	*- FN
15	1		*BONNET SEAL	Not Necessary	125.50 FN	*- FN
16	1		*BONNET INSULATOR	Not Necessary	350.10 FN	*- FN
17	2		*FRONT SUSPENSION L-R	Not Necessary	1,980.00 FN	*- FN
18	1		*FRONT TYRE N/S	Serviceable	300.00 FS	*- FS
19	1		*FRONT RIM N/S	Repair	550.00 FS	*- FS
20	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
21	4		*FRONT BUMPER SENSOR	Repeated	1,520.00 FS	*- FS
22	2		*FRONT BUMPER SIDE MOUNT - L-R	Not Necessary	194.40 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	22,124.80	5,579.85
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,970.48	552.99
Total Parts (S\$)	20,154.32	5,026.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND RENEW BONNET, FRONT BUMPER	New	800.00	500.00
2	TO RESPRAY REPLACED AND AFFECTED PANEL FRONT BUMPER, BONNET	New	900.00	400.00
3	TO CARRY OUT ANTI RUST TREATMENT	New	200.00	0.00
4	TO CHECK WIRING FOR PROPER FUNCTION }	New	150.00	20.00
5	TO CHECK ADJUST HEADLAMP HEIGHT }	New	90.00	0.00
6	TO CARRY OUT WHEEL ALIGNMENT	New	120.00	60.00
7	TO PROVIDE TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			2,360.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >