



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FT 7719M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER	NOT NECESSARY	\$75.00	\$0.00
1	FRONT O/S SIGNAL	NOT NECESSARY	\$68.00	\$0.00
1	O/S SIDE MIRROR	NOT NECESSARY	\$80.00	\$0.00
1	HANDLE-BAR	REPLACED	\$145.00	\$145.00
1	BRAKE LEVER	REPLACED	\$28.00	\$28.00
1	SET HAND GRIP	NOT NECESSARY	\$80.00	\$0.00
1	FRONT O/S FOOTREST	NOT NECESSARY	\$42.00	\$0.00
1	FRONT O/S FOOTREST BRACKET	NOT NECESSARY	\$60.00	\$0.00
1	BRAKE PEDAL	NOT NECESSARY	\$55.00	\$0.00
1	REAR O/S FOOTREST	NOT NECESSARY	\$42.00	\$0.00
1	EXHAUST PIPE ASSY	NOT NECESSARY	\$655.00	\$0.00
1	EXHAUST END COVER	NOT NECESSARY	\$68.00	\$0.00
1	EXHAUST PROTECTOR - BLACK	REPLACED	\$75.00	\$75.00
1	CHAIN COVER	NOT NECESSARY	\$85.00	\$0.00
1	REAR O/S TAILBOARD	REPLACED	\$155.00	\$155.00
2	REAR SIGNALS	REPLACED	\$136.00	\$136.00
1	REAR FENDER	REPLACED	\$95.00	\$95.00
1	REAR FENDER INNER BRACKET	REPLACED	\$85.00	\$85.00
1	REAR TAILLAMP	REPLACED	\$135.00	\$135.00
1	REAR RIM	NOT NECESSARY	\$550.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$271.40)	(\$85.40)
			<b>\$2,442.60</b>	<b>\$768.60</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	REPLACED	\$28.00	\$15.00
1	REAR BOX (SN)	NOT NECESSARY	\$280.00	\$0.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	\$120.00	\$0.00
1	REAR TYRE (DEPRECIATION) (SN)	NOT NECESSARY	\$400.00	\$0.00
			<b>\$828.00</b>	<b>\$15.00</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PROVIDE TOWING SERVICE	NOT NECESSARY	\$50.00	\$0.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP		\$80.00	\$20.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT		\$480.00	\$250.00
			\$610.00	\$270.00
GRAND TOTAL			\$3,880.60	\$1,053.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$850.00
Report Ref No: CS/CTI24080052/Rvh3e2				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.