



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNC 9801P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDE DOOR MIRROR ASSY OUTER (R) (NOT NECESSARY)	NOT CONSISTENT WITH THE IMPACT	\$835.00	\$0.00
1	SIDE DOOR MIRROR COVER (R) (SIGNAL LAMP)	CUT	\$130.00	\$130.00
1	SIDE DOOR MIRROR RETRACTOR (R)	NOT NECESSARY	\$460.00	\$0.00
1	SIDE DOOR MIRROR GLASS (R)	NOT NECESSARY	\$372.00	\$0.00
1	SIDE DOOR MIRROR ASSY INNER (R)	NOT NECESSARY	\$340.00	\$0.00
	<b>LESS 20.00 / 25.00% DISCOUNT</b>		(\$427.40)	(\$32.50)
			\$1,709.60	\$97.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	MIRROR ASSY SCREW (S) (SN)	NOT NECESSARY	\$40.00	\$0.00
1	MIRROR ASSY BOLT (S) (SN)	NOT NECESSARY	\$45.00	\$0.00
			\$85.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO INSPECT & IDENTIFY DAMAGED WIRING FROM PRIMARY ELECTRICAL HOUSING (ECU)	NOT NECESSARY	\$150.00	\$0.00
	TO RECTIFY & REMOVE AND/OR REPLACE DAMAGED WIRING IN MIRROR ASSY	NOT NECESSARY	\$250.00	\$0.00
	TO REMOVE & REPLACE DAMAGED WIRING IN MIRROR ASSY	NOT NECESSARY	\$120.00	\$0.00
	TO REPLACE AND/OR REPACK WIRING SETUPS FROM ECU		\$120.00	\$50.00
	TO DIAGNOSE POST REPLACEMENT CONFIGURATION OF NEW WIRING AT MIRROR ASSY TO PRIMARY ELECTRICAL HOUSING (ECU)	NOT NECESSARY	\$200.00	\$0.00
	TO SPRAY VEHICLE BODY REPLACE BODY PANELS, DAMAGED PANELS AND PANELS COHERANT TO ACCIDENT		\$500.00	\$80.00
	TO PROVIDE PROFESSIONAL LABOUR, WORKMANSHIP TO REPLACE, REPAIR, REALIGN TO UNIFORM STRUCTURE OF ALL AND/OR		\$500.00	\$80.00
	TO REMOVE & REPLACE SIDE MIRROR ASSY, RE-ALIGN BODYWORK FITMENT	NOT NECESSARY	\$200.00	\$0.00
	TO DISMANTLE & REPLACE AND/OR REPAIR REAR INTERNAL MIRROR PANEL ASSEMBLY	NOT NECESSARY	\$200.00	\$0.00
			\$2,240.00	\$210.00

<b>GRAND TOTAL</b>			<b>\$4,034.60</b>	<b>\$307.50</b>
--------------------	--	--	-------------------	-----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

	RECOMMENDED COST OF REPAIRS		\$307.50
Report Ref No: CS/FCI24080055/Enp3			

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.