

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days

5b.

B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24080055/Enp3	
	16 RAFFLES QUA		Date:	05/08/2024	
	#42-01 HONG LEC SINGAPORE 0485	DNG BUILDING 81	Code:	FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 1680U	Veh. Inspected	SNC 9801P	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24006807MFCT	Excess	\$0.00	
	Assign From	BETTY	Assign Date	05/08/2024	
2. Vehicle Details					
	Make & Model	TOYOTA PRIUS	C.C	1798	
	Engine No.	2ZR2N59602	Year of Reg.	29/11/2021	
	Chassis No.	JTDKB3FU803096084	Colour	SILVER	
	Odometer	194515 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65 R15	WANDA	6	
	L/H Front Tyre	195/65 R15	WANDA	6	
	R/H Rear Tyre	195/65 R15	WANDA	6	
	L/H Rear Tyre	195/65 R15	WANDA	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	31/07/2024	Inspection Date	05/08/2024	
	Survey held at	Survey held at MIRAI AUTO PERFORMANCE PTE LTD - 53 UBI AVE 1, #01-33 PAYA UBI INDUSTRIAL PARI SINGAPORE 408934			
5a. Remarks					

Estimate Days of Repair