



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKQ 6763Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED / DEFORMED	\$1,235.30	\$801.20
1	REAR BUMPER RETAINER LH	NOT NECESSARY	\$225.00	\$0.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	\$255.00	\$0.00
1	REAR BUMPER BRACKET LH	NOT NECESSARY	\$187.00	\$0.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	\$187.00	\$0.00
1	REAR BUMPER LOWER GRILLE	NO SUCH PARTS	\$475.00	\$0.00
1	REAR END PANEL	DENTED / BENT	\$955.00	\$665.30
2	END PANEL CENTRA BRACKET	NO SUCH PARTS	\$320.00	\$0.00
1	REAR END PANEL TOP GARNISH	TWISTED	\$689.00	\$322.10
1	REAR LAMP LH	NOT NECESSARY	\$998.40	\$0.00
1	REAR LAMP BRACKET LH	NOT NECESSARY	\$225.00	\$0.00
1	REAR LAMP RH	NOT NECESSARY	\$998.40	\$0.00
1	REAR LAMP BRACKET RH	NOT NECESSARY	\$225.00	\$0.00
1	SENSOR ANTENNA	CRACKED	\$689.00	\$285.40
1	TAILGATE	TO REPAIR SEE LABOUR	\$2,251.00	\$0.00
1	TAILGATE RUBBER	NOT NECESSARY	\$328.50	\$0.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	\$245.20	\$0.00
1	TAILGATE INNER LOCK	NOT NECESSARY	\$545.00	\$0.00
2	TAILGATE HINGE	NOT NECESSARY	\$285.00	\$0.00
	LESS 25.00% DISCOUNT		(\$2,829.70)	(\$518.50)
			\$8,489.10	\$1,555.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	\$90.00	\$0.00
1	SET REVERSE SENSOR (SN)	SERVICEABLE	\$480.00	\$0.00
			\$620.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REFIX REAR REVERSE SENSOR	NOT NECESSARY	\$120.00	\$30.00
	CHECK ALL WIRING AND LIGHTING SYSTEM		\$240.00	\$20.00
	REMOVE AND REFIT REAR WINDSCREEN		\$240.00	\$0.00
	REMOVE AND REFIT FRONT AND REAR LINING,TRIM AND GARNISH		\$300.00	\$60.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE		\$1,500.00	\$600.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,500.00	\$680.00
	APPLY ANTI RUST ON AFFECTED AREAS		\$150.00	\$30.00
			\$4,050.00	\$1,420.00
GRAND TOTAL			\$13,159.10	\$3,005.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,400.00
Report Ref No: CS/INC24080060/Unh3				

TOTAL FOR SPARE PARTS: \$ 9,109.10 \$ 1,585.50
TOTAL FOR LABOUR : \$ 4,050.00 \$ 1,420.00
TOTAL REPAIR COST: \$ 13,159.10 \$ 3,005.50

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.