



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 3231E

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT COVER (N)	TO REPAIR SEE LABOUR	\$1,938.90	\$0.00
1	REAR BOOT COVER WEATHER STRIPE (N)	NOT NECESSARY	\$118.50	\$0.00
1	REAR BOOT COVER EMBLEM 'EPOWER' (N)	NECESSARY	\$105.00	\$105.00
1	REAR BOOT COVER EMBLEM 'HIGHWAY STAR' (N)	NECESSARY	\$84.90	\$84.90
1	REAR BOOT COVER CHROME MOULDING (N)	NOT NECESSARY	\$887.30	\$0.00
1	REAR BUMPER QUARTER PANEL (N)	TO REPAIR SEE LABOUR	\$428.90	\$0.00
1	REAR BUMPER FASCIA (N)	TORN	\$1,574.00	\$1,574.00
1	SET REAR BUMPER CLIPS (N)	NECESSARY	\$50.00	\$50.00
2	REAR BUMPER SENSOR (LH & CENTRE OUTER) @\$258.20 (N)	SERVICEABLE	\$516.40	\$0.00
2	REAR BUMPER SIDE RETAINER L&R (HORIZONTAL) @\$36.20 (N)	NOT NECESSARY	\$72.40	\$0.00
2	REAR BUMPER SIDE RETAINER L&R (VERTICAL) @\$36.20 (N)	NOT NECESSARY	\$72.40	\$0.00
2	REAR BUMPER LOWER SIDE BRACKET L&R @\$36.20 (N)	NOT NECESSARY	\$72.40	\$0.00
1	TAIL LAMP RH (N) (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	\$623.90	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$181.39)
			\$6,545.00	\$1,632.51

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER LIP (SN)	CUT	\$1,300.00	\$1,300.00
2	REAR BUMPER INNER BRACKET L&R @\$107.10 (SN) (ADDITIONAL)	NECESSARY	\$214.20	\$214.20
2	REAR BUMPER OUTER BRACKET L&R @\$107.10 (SN) (ADDITIONAL)	NECESSARY	\$214.20	\$214.20
			\$1,728.40	\$1,728.40

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CUT OUT, RENEW, KNOCKING & WELDING REAR BOOT COVER, REAR QUARTER PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF REAR BOOT COVER AND REAR BUMPER QUARTER PANEL		\$1,080.00	\$400.00
	TUFF-KOTE ON DAMAGE PARTS	NOT NECESSARY	\$40.00	\$0.00
	SPRAY PAINTING ON DAMAGE PARTS		\$1,580.00	\$500.00
	REMOVE & REFIX REAR BUMPER SENSOR		\$80.00	\$30.00
	CHECK ALL LIGHTING AFTER REPAIRS		\$40.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	COATING		\$800.00	\$360.00
			\$3,620.00	\$1,310.00
GRAND TOTAL			\$11,893.40	\$4,670.91
	RECOMMENDED COST OF REPAIRS			\$4,670.91
Report Ref No: CS/AGI24060089/Unh3m4				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.