



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJY 3207B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/TORN	\$2,250.00	\$1,275.05
1	FRONT BUMPER RETAINER LH	CRACKED	\$175.00	\$62.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	\$175.00	\$0.00
1	FRONT BUMPER GRILLE RH	NOT NECESSARY	\$988.00	\$0.00
1	FRONT BUMPER CENTER GRILLE	NOT NECESSARY	\$758.20	\$0.00
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	\$985.00	\$0.00
1	FRONT FENDER INNER SHIELD LH	TORN	\$425.00	\$180.50
1	FRONT HEADLAMP LH	HOLDER CRACKED	\$2,245.00	\$1,883.60
	LESS 10.00% DISCOUNT		(\$800.12)	(\$340.12)
			\$7,201.08	\$3,061.03

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT NUMBER PLATE (SN)	NOT NECESSARY	\$90.00	\$0.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT FENDER CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT PARKING SENSOR (SN)	NOT NECESSARY	\$480.00	\$0.00
1	SET RIM (SN)	TO REPAIR SEE LABOUR	\$1,200.00	\$0.00
			\$1,920.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK FRONT WIRING AND LIGHTNING SYSTEM		\$200.00	\$20.00
	REMOVE, REFIT FRONT LINING, TRIM AND GARNISH	NOT NECESSARY	\$300.00	\$0.00
	REMOVE AND RENEW FRONT REVERSE SENSOR	NOT NECESSARY	\$150.00	\$0.00
	PANEL BEATING ON FRONT AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND RIM		\$1,000.00	\$400.00
	SPRAY PAINTING ON FRONT AFFECTED AREAS		\$1,000.00	\$550.00
	APPLY ANTI RUST ON AFFECTED AREAS	NOT NECESSARY	\$120.00	\$0.00
			\$2,770.00	\$970.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$11,891.08	\$4,061.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$3,200.00
Report Ref No: CS/INC24080061/Uqh3			

TOTAL FOR SPARE PARTS: \$ 9,121.08 \$ 3,091.03
TOTAL FOR LABOUR : \$ 2,770.00 \$ 970.00
TOTAL REPAIR COST: \$ 11,891.08 \$ 4,061.03

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.