

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080065/KUA3Q2**Date:** 14/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : SDU9908P **Insured Vehicle No :** SLK9732L
Date of Loss: 02/08/2024 Nature of Claim: TP Claim No: MFL2024D0008936

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDU9908P**
Make & Model: TOYOTA SIENTA, 1.5 HYBRID G CVT (A) Engine No: M15AY485543
Reg. Date: 21/07/2023 (Man. Year: 2022) Chassis No: MXPL101010047
Colour: Blue Odometer: 120156 km
Engine Capacity: 1490 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: TRISTAR 7 mm Rear Left Side: TRISTAR 8 mm
Front Right Side: TRISTAR 7 mm Rear Right Side: TRISTAR 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,758.17	6,736.95	4,021.22	37.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	2,160.00	2,510.00	53.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,428.17	8,896.95	6,531.22	42.33
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	15,428.17	7,100.00	8,328.17	53.98
+ GST 9.00/9.00% (S\$)	1,388.54	639.00	749.54	53.98
Nett Amount (S\$)	16,816.71	7,739.00	9,077.71	53.98
+ Loss of Use (11.0 x S\$80.00/day) (S\$)		880.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,646.25		
Global Sum Settlement (S\$)		8,600.00		

INSPECTION

Date of Assignment: 06/08/2024
Date Inspected: 06/08/2024 Inspected At: Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721
Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2024)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDU9908P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cut	1,250.20 FL	*1,171.80 FL
2	1		*FRONT BUMPER LH SIDE GARNISH	Scratched	181.20 FL	*181.20 FL
3	3		*FRONT BUMPER LH SIDE GARNISH CLIP	Necessary	24.00 FL	*24.00 FL
4	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	121.50 FL	*121.50 FL
5	1		*FRONT LH HEADLAMP	Mtg Cracked	1,580.50 FL	*1,580.50 FL
6	1		*FRONT LH FENDER	Bent	685.50 FL	*685.50 FL
7	1		*FRONT LH FENDER INNER SHIELD	Distorted	281.50 FL	*281.50 FL
8	10		*FRONT LH FENDER INNER SHIELD CLIP	Necessary	50.00 FL	*50.00 FL
9	1		*FRONT LH FENDER TOP GARNISH	Serviceable	181.20 FL	*- FL
10	1		*FRONT LH WHEEL HOUSE OUTER PANEL	Repair	385.50 FL	*- FL
11	1		*FRONT LH RIM	Dented	581.50 FL	*581.50 FL
12	1		*FRONT LH RIM HALF CAP	Missing	158.20 FL	*158.20 FL
13	1		*FRONT LH KNUCKLE ARM	Bent	481.50 FL	*481.50 FL
14	1		*FRONT LH KNUCKLE BEARING	Necessary	425.20 FL	*301.00 FL
15	1		*FRONT LH ABSORBER	Bent	450.50 FL	*450.50 FL
16	1		*FRONT LH LOWER ARM	Distorted	381.50 FL	*381.50 FL
17	1		*FRONT LH LINKAGE	Distorted	181.50 FL	*181.50 FL
18	1		*FRONT LH SIDE MIRROR	Repair	581.50 FL	*- FL
19	1		*FRONT LH SIDE MIRROR COVER	Repair	195.20 FL	*- FL
20	1		*FRONT LH DOOR	Bent	985.20 FL	*985.20 FL
21	1		*FRONT LH DOOR PRILLE	Repair	985.20 FL	*- FL
22	2		*FRONT LH DOOR HINGE	Repair	363.00 FL	*- FL
23	1		*FRONT LH DOOR PROTECTOR	Cut	281.50 FL	*281.50 FL
24	8		*FRONT LH DOOR PROTECTOR CLIP	Necessary	40.00 FL	*40.00 FL
25	1		*FRONT LH DOOR INNER LOCK	Dented	481.50 FL	*481.50 FL
26	1		*FRONT LH DOOR INNER RUBBER	Serviceable	281.20 FL	*- FL
27	1		*FRONT LH DOOR GLASS MOTOR & GEAR	Serviceable	481.20 FL	*- FL
28	1		*FRONT LH DOOR FIRM STICKER	Necessary	121.50 FL	*121.50 FL
29	1		*REAR LH DOOR	Repair	1,250.20 FL	*- FL
30	1		*REAR LH DOOR PROTECTOR	Cut	281.20 FL	*281.20 FL
31	1		*REAR LH DOOR FILM STICKER	Not Necessary	121.50 FL	*- FL
32	1		*FRONT LH TYRE (60%) (\$200.00)	Cut	250.00 FS	*120.00 FS
33	1		*SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,220.90	8,942.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,462.73	2,205.65
Total Parts (\$\$)	10,758.17	6,736.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT DASHBOARD	New	350.00	0.00
2	REMOVE & REFIX FRONT LH UNDERCARRIAGE	New	380.00	200.00
3	REMOVE & REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
4	REMOVE & REFIT LH 2 DOOR GLASS	New	150.00	60.00
5	TOWING FEE	New	120.00	60.00
6	ALIGNMENT	New	80.00	60.00
7	TUFF KOTE	New	120.00	60.00
8	WIRING	New	150.00	20.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
10	LABOUR CHARGES	New	1,600.00	700.00
Gross Labour Cost (\$\$)			4,670.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >