



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PC 2457Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	MTG CRACKED	\$1,987.50	\$788.10
1	FRONT BUMPER BRACKET LH	CRACKED	\$224.00	\$162.50
1	HEADLAMP LH	MTG DISTORTED	\$2,986.00	\$1,248.00
1	FRONT DOOR LH	BENT/WARPED	\$2,280.00	\$1,788.20
1	FRONT LH DOOR SIDE PANEL	BENT	\$1,150.00	\$781.20
1	FRONT STEP PANEL LH	DENTED	\$480.00	\$198.10
1	SLIDE DOOR LH	BENT/WARPED	\$2,785.00	\$1,655.10
1	FRONT STEP PANEL LOWER LH	TO REPAIR SEE LABOUR	\$580.00	\$0.00
1	LH ROCKER PANEL	TO REPAIR SEE LABOUR	\$1,650.00	\$0.00
1	REAR LH CENTER PANEL	TO REPAIR SEE LABOUR	\$1,978.50	\$0.00
1	REAR LH PANEL	TO REPAIR SEE LABOUR	\$3,985.00	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$5,021.50)	(\$1,655.30)
			\$15,064.50	\$4,965.90

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
4	TUBE LH SIDE PANEL GLASS SEALANT (SN)	NOT NECESSARY	\$240.00	\$0.00
1	EXCURSION BUS (SN)	NECESSARY	\$120.00	\$35.00
1	FRONT RIM LH (SN)	SERVICEABLE	\$400.00	\$0.00
1	REAR RIM LH (SN)	SERVICEABLE	\$400.00	\$0.00
			\$1,160.00	\$35.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO DO CUTTING, WELDING, REMOVE TRACK, ALIGN ADJUST ON ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT STEP PANEL LOWER LH, LH ROCKER PANEL, REAR LH CENTER PANEL AND REAR LH PANEL		\$1,600.00	\$900.00
	TO REMOVE REFIX CAR SEAT, INNER GARNISH, UPHOLSTERY ETC		\$350.00	\$100.00
	TO REMOVE REFIX SIDE PANEL GLASS, SIDE SLIDE DOOR GLASS LEFT	NOT NECESSARY	\$280.00	\$0.00
	TRANSFER DOOR AND SLIDE DOOR TO ANOTHER DOOR		\$300.00	\$120.00
	ANTI RUST		\$140.00	\$90.00
	TO DO WHEEL ALIGNMENT	NOT NECESSARY	\$80.00	\$0.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING SYSTEM		\$120.00	\$20.00
	TO DO SPRAY PAINTING FOR ACCIDENT AREA INNER AND OUTER		\$1,600.00	\$1,200.00
			\$4,470.00	\$2,430.00
GRAND TOTAL			\$20,694.50	\$7,430.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,900.00
Report Ref No: CS/AGI24080066/Kqp3				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.