

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080067/KPA3Q2
Date: 19/09/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002592_01
Claimant Vehicle No : SHD9500Z Insured Vehicle No : SNB7328H
Date of Loss: 13/07/2024 Nature of Claim: TP Claim No: MFL2024D0008368

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9500Z
Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C22903
Reg. Date: 31/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU403080996
Colour: Metallic Pearl White/Red Odometer: 599815 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Sailun 8 mm Rear Left Side: Grenlander 9 mm
Front Right Side: Sailun 8 mm Rear Right Side: Grenlander 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,301.13	2,181.96	3,119.17	58.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	890.00	4,100.00	82.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,291.13	3,071.96	7,219.17	70.15
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	10,291.13	2,450.00	7,841.13	76.19
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/08/2024
Date Inspected: 06/08/2024 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9500Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
2	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	902.16 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
4	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
5	1		*UNIT ASSY ,HEADLAMP RH	Serviceable	2,637.60 FL	*- FL
6	1		*LAMP ASSY ,FOG RH	Cut	1,200.78 FL	*1,200.78 FL
7	1		*FENDER SUB-ASSY ,FRONT RH	Bent	977.80 FL	*977.80 FL
8	1		*LINER ,FRONT FENDER RH	Serviceable	206.70 FL	*- FL
9	1		*FRONT FENDER EMBLEM RH	Necessary	54.60 FL	*54.60 FL
10	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
11	1		*FRT BUMPER SIDE RETAINER CLIP	Not Necessary	65.00 FS	*- FS
12	1		*FENDER LINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,999.84	2,889.28
- List Item Discount on L Items 25.00/25.00% (S\$)	1,698.71	707.32
Total Parts (S\$)	5,301.13	2,181.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF FRONT FENDER PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			4,990.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >