

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24080072/ANP3M4**Date:** 28/10/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SKG3193P **Insured Vehicle No :** GBM5256D
Date of Loss: 02/08/2024 Nature of Claim: TP Claim No: DMCV2400154H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG3193P**
Make & Model: MERCEDES-BENZ C180, 1.6 Kompressor (A) Engine No: 27191031347853
Reg. Date: 25/10/2011 (Man. Year: 2011) Chassis No: WDD2040452A606207
Colour: White Odometer: 347132 km
Engine Capacity: 1597 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,631.50	5,619.20	8,012.30	58.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,990.00	1,210.00	4,780.00	79.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,621.50	6,829.20	12,792.30	65.20
Approved Total (Overridden) (S\$)		5,450.00		
(S\$)	19,621.50	5,450.00	14,171.50	72.22
+ GST 9.00/9.00% (S\$)	1,765.94	490.50	1,275.44	72.22
Nett Amount (S\$)	21,387.44	5,940.50	15,446.94	72.22

INSPECTION

Date of Assignment: 05/08/2024
Date Inspected: 05/08/2024 Inspected At: HD PERFECT AUTOWORK PTE LTD (HQ)
8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT
SINGAPORE 415875
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2024)
Parts:	143	MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG3193P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,010.00 FL	*1,540.00 FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	85.00 FL	*- FL
3	1		*REAR BUMPER CENTER MOULDING	Cracked	185.00 FL	*185.00 FL
4	1		*REAR BUMPER CORNER BRACKET	N/S Cracked	358.00 FL	*90.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Not Necessary	148.00 FL	*- FL
6	2		*REAR BUMPER LOWER BRACKET (CENTER)	Not Necessary	130.00 FL	*- FL
7	1		*REAR BUMPER SIDE INNER GARNISH	Not Necessary	285.00 FL	*- FL
8	1		*REAR BUMPER CENTRE FRAME	Not Necessary	342.00 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	658.00 FL	*658.00 FL
10	1		*TAILLAMP	N/S Cracked	1,524.00 FL	*762.00 FL
11	2		*REAR FENDER DRAIN GARNISH	Not Necessary	196.00 FL	*- FL
12	2		*REAR FENDER COWLING	Not Necessary	396.00 FL	*- FL
13	2		*REAR FENDER INNER TRIM	Not Necessary	850.00 FL	*- FL
14	1		*BOOTLID	Dented	2,450.00 FL	*1,874.00 FL
15	1		*BOOTLID CENTER MOULDING	Not Necessary	195.00 FL	*- FL
16	1		*BOOTLID LOGO	Necessary	64.00 FL	*64.00 FL
17	1		*BOOTLID EMBLEM C180	Necessary	86.00 FL	*86.00 FL
18	1		*BOOTLID EMBLEM KOMPRESSOR	Necessary	155.00 FL	*155.00 FL
19	4		*BOOTLID STOPPER	Not Necessary	180.00 FL	*- FL
20	2		*BOOTLID HINGE	Not Necessary	262.00 FL	*- FL
21	1		*BOOTLID INSULATOR	Not Necessary	598.00 FL	*- FL
22	1		*BOOTLID TOP LOCK	Not Necessary	300.00 FL	*- FL
23	1		*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
24	1		*BOOTLID WEATHER STRIP	Cut	189.00 FL	*189.00 FL
25	1		*BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	168.00 FL	*- FL
26	1		*BOOTLID INNER HANDLE GARNISH	Not Necessary	128.00 FL	*- FL
27	1		*REAR END PANEL	Repair	1,460.00 FL	*- FL
28	1		*REAR END PANEL INNER GARNISH	Cracked	285.00 FL	*285.00 FL
29	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
31	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR BUMPER LOWER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
33	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
35	1		*BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
36	1		*SET BOOTLID NUMBER PLATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
37	1		*BOOTLID EMBLEM C&C (SPECIAL TYPE)	Necessary	120.00 FS	*50.00 FS
38	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
39	1		*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
40	1		*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
41	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
42	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
43	1		*SET REAR END PANEL INNER GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
44	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,005.00 6,208.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,373.50	588.80
Total Parts (S\$)					13,631.50	5,619.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,200.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	350.00	30.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	380.00	40.00
6	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX AND RESET REVERSE SENSOR	New	250.00	50.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	650.00	0.00
Gross Labour Cost (\$\$)			5,990.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >