



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJA 1323M

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR-LH	TO REPAIR SEE LABOUR	\$1,895.60	\$0.00
1	FRONT DOOR SIDE MIRROR	DAMAGED	\$1,210.65	\$1,210.65
1	FRONT DOOR SIDE MIRROR COVER	NOT NECESSARY	\$181.35	\$0.00
1	FRONT DOOR GLASS	NOT NECESSARY	\$1,055.90	\$0.00
1	FRONT DOOR GLASS OUTER MOULDING	NOT NECESSARY	\$181.60	\$0.00
	LESS 25.00% DISCOUNT		(\$1,131.28)	(\$302.66)
			\$3,393.82	\$907.99

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING AND ETC		\$600.00	\$200.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR - LH.		\$500.00	\$200.00
			\$1,100.00	\$400.00

GRAND TOTAL	\$4,493.82	\$1,307.99
--------------------	-------------------	-------------------

RECOMMENDED COST OF REPAIRS (CONFIRMED)	\$1,307.99
--	-------------------

Report Ref No: CS/INC24080074/Unh3

TOTAL FOR SPARE PARTS: \$ 3,393.83 \$ 907.99
TOTAL FOR LABOUR : \$ 1,100.00 \$ 400.00
TOTAL REPAIR COST: \$ 4,493.83 \$ 1,307.99

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.