

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	INCOME INCUES	Affiliated to Federation Intern		
WS	INCOME INSURA		Ref:	CS/INC24080074/Unh3
	75 BRAS BASAH INCOME CENTRE	ROAD ESINGAPORE 189557	Date:	12/08/2024
			Code:	INC
۱.		Policy Particula	ars :- THIRD PARTY CLA	AIM
	Insured Veh.	FBL 8416U	Veh. Inspected	SJA 1323M
	Policy No.	-	Coverage	0
	Claim No.	MT/1289025-002	Excess	\$0.00
	Assign From	EILEEN LEE	Assign Date	06/08/2024
2.		Ve	ehicle Details	
	Make & Model	TOYOTA SIENTA (A)	C.C	1496
	Engine No.	2NRX544253	Year of Reg.	29/01/2020
	Chassis No.	MHFZ28H3100068326	Colour	GREY
	Odometer	103355 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.		Con	ditions of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	195/50R16	TOURADOR	6
	L/H Front Tyre	195/50R16	TOURADOR	6
	R/H Rear Tyre	195/50R16	TOURADOR	6
	L/H Rear Tyre	195/50R16	TOURADOR	6
4.		Descri	ption of Damages	
HE	VEHICLE SUSTAI	NED DAMAGES AT THE N/S BOD	Y.	
ΑN	AGES SEE DETAI	LS.		
5.		Gene	eral Information	
	Accident Date	01/08/2024	Inspection Date	06/08/2024 (10:28)
	<u> </u>	SOON BENG MOTOR - 1 KAKI	BUKIT AVENUE 6 #01-9	6 AUTOBAY @ KAKI BUKIT
	Survey held at	SINGAPORE 417883		J

Estimate Days of Repair