

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKM 8999S

REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR BUMPER	BUCKLED	\$1,440.00	\$1,440.00	
1	LOWER REAR BUMPER	CUT	\$390.00	\$355.00	
1	COVER TOWING EYE	CRACKED	\$93.00	\$93.00	
1	BRACKET, REAR CENTER OF BUMPER	CRACKED	\$346.00	\$210.00	
1	BUMPER BASE BRACKET, MIDDLE PART OF REAR BUMPER	CRACKED	\$345.00	\$345.00	
1	BRACKET RIGHT SIDE	SERVICEABLE	\$76.00	\$0.00	
1	BRACKET, RIGHT TAIL PIPE	TO REPAIR SEE LABOUR	\$65.00	\$0.00	
2	REAR PARKING SENSOR	SHORTED	\$390.00	\$390.00	
1	LUGGAGE COMPARTMENT SWITCH MODULE TOP SENSOR CODE A	SERVICEABLE	\$160.00	\$0.00	
1	LUGGAGE COMPARTMENT SWITCH MODULE BOTTOM SENSOR CODE B	SERVICEABLE	\$205.00	\$0.00	
	LESS / 10.00% DISCOUNT		\$0.00	(\$283.30)	
			\$3,510.00	\$2,549.70	
	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	SET BUMPER CLIP (SN)	NECESSARY	\$40.00	\$40.00	
			\$40.00	\$40.00	
Labour					
	Labo	ur			
	Description of Parts	ur Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
			Workshop Estimate (\$) \$200.00	Our Adjusted (\$) \$60.00	
	Description of Parts				
	Description of Parts TO REMOVE & REFIT PDC SENSOR	Condition	\$200.00	\$60.00	
	Description of Parts TO REMOVE & REFIT PDC SENSOR TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR TO PANEL BEAT / RE-ALIGNMENT. INCLUSIVE OF THE REPAIR OF	Condition	\$200.00 \$200.00	\$60.00 \$0.00	
	Description of Parts TO REMOVE & REFIT PDC SENSOR TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR TO PANEL BEAT / RE-ALIGNMENT. INCLUSIVE OF THE REPAIR OF BRACKET, RIGHT TAIL PIPE	Condition	\$200.00 \$200.00 \$600.00	\$60.00 \$0.00 \$400.00	
	Description of Parts TO REMOVE & REFIT PDC SENSOR TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR TO PANEL BEAT / RE-ALIGNMENT. INCLUSIVE OF THE REPAIR OF BRACKET, RIGHT TAIL PIPE	Condition	\$200.00 \$200.00 \$600.00	\$60.00 \$0.00 \$400.00 \$450.00	
	Description of Parts TO REMOVE & REFIT PDC SENSOR TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR TO PANEL BEAT / RE-ALIGNMENT. INCLUSIVE OF THE REPAIR OF BRACKET, RIGHT TAIL PIPE TO SPRAY PAINTING	Condition	\$200.00 \$200.00 \$600.00 \$1,600.00	\$60.00 \$0.00 \$400.00 \$450.00 \$910.00	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.