

ASS. REC. BY:

REF:

AG21 CS/AGI24080076/Kvp3e2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured: SJK 3383Z

Policy No.

Claims No. C10030829/JK

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/8/21 Rm @ 2800k Cdn (red 2350,45%)

Veh No:

SKM 8999S

Yr Regn:

03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E250

c.c

1991

Colour

N. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

103923

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2120362B 146987

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

245/40 R18

R: 7

265/35 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

29/7/24

D.O.I.

7/8/2024

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

COLOUR VIBE PTE. LTD.

176 Sin Ming Dr, #05-16 Sin Ming AutoCare, Singapore 575721

Company Registration No: 202203460Z

Email: business@colourvibe.sg

Contact: (+65) 94594918

Not with insurance
L1 Reg & 2800h
Bumper After Painting
4 days

Car Make/Model: MERCEDES E250 SEDAN (R18)

Date: 30/07/2024

Engine/Chassis No: WDD2120362B146987

Carplate : SKM8999S

LIST ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
REAR BUMPER	1	\$ 1,440.00	\$ <i>Per</i> 1,440.00 ✓
LOWER REAR BUMPER <i>355</i>	1	\$ 390.00	\$ <i>CM</i> 390.00 ✓
COVER TOWING EYE	1	\$ 93.00	\$ <i>CM</i> 93.00 ✓
BRACKET, REAR CENTER OF BUMPER <i>210</i>	1	\$ 346.00	\$ <i>CM</i> 346.00 ✓
BUMPER BASE BRACKET, MIDDLE PART OF REAR BUMPER	1	\$ <i>CM</i> 345.00	\$ <i>Per</i> 345.00 ✓
BRACKET RIGHT SIDE	1	\$ 76.00	\$ <i>Per</i> 76.00 ✓
BRACKET, RIGHT TAIL PIPE	1	\$ 65.00	\$ <i>Per</i> 65.00 ✓
REAR PARKING SENSOR	2	\$ 195.00	\$ <i>Short</i> 390.00 ✓
Luggage compartment switch module Top sensor code A	1	\$ 160.00	\$ <i>Per</i> 160.00 ✓
Luggage compartment switch module Bottom sensor code B	1	\$ 205.00	\$ <i>Per</i> 205.00 ✓

SPECIAL NETT ITEM			
DESCRIPTION	QUANTITY	PRICE	TOTAL
BUMPER CLIP (SET)	1	\$ 40.00	\$ <i>Per</i> 40.00 ✓

LABOUR CHARGE			
DESCRIPTION	QUANTITY	PRICE	TOTAL
TO REMOVE & REFIT PDC SENSOR	1	\$ 200.00	\$ 200.00 <i>600</i>
TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	1	\$ 200.00	\$ <i>na</i> 200.00 <i>x</i>
TO PANEL BEAT/ RE-ALIGNMENT	1	\$ 600.00	\$ 600.00 <i>4000</i>
TO SPRAY PAINTING	1	\$ 600.00	\$ 600.00 <i>4500</i>

TOTAL	\$ 5,150.00
-------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: