

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080079/UUA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100685359
Claimant Vehicle No : SLN8958T **Insured Vehicle No :** SGL8370H
Date of Loss: 02/08/2024 Nature of Claim: TP Claim No: 1535043129SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN8958T**
Make & Model: HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) Engine No: L15B31191298
Reg. Date: 22/05/2017 (Man. Year: 2016) Chassis No: JHMGK5850HX201911
Colour: White Odometer: 151000 km
Engine Capacity: 1498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,956.56	1,930.48	2,026.08	51.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	700.00	1,020.00	59.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,676.56	2,630.48	3,046.08	53.66
Approved Total (Overridden) (S\$)		2,100.00		
Nett Amount (S\$)	5,676.56	2,100.00	3,576.56	63.01
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		2,220.00		

INSPECTION

Date of Assignment: 07/08/2024
Date Inspected: 07/08/2024 Inspected At: Leang Automotive (HQ)
1 KAKI BUKIT AVE 6, #01-68 AUTOBAY@KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	567.50 FL	*567.50 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Not Necessary	28.90 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	213.10 FL	*- FL
4	1		*FRONT FENDER O/S	Repair	445.20 FL	*- FL
5	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	168.60 FL	*- FL
6	1		*FRONT LOWER ARM O/S	Not Necessary	331.80 FL	*- FL
7	1		*FRONT KNUCKLE ARM O/S	Not Necessary	392.50 FL	*- FL
8	1		*FRONT KNUCKLE ARM BEARING O/S	Not Necessary	215.00 FL	*- FL
9	1		*HEADLAMP O/S	Scratched / Cracked	1,283.10 FL	*1,283.10 FL
10	1		*SET FRONT BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
11	1		*FRONT SPORT RIM O/S	Cut / Damaged	800.00 FS	*450.00 FS
12	1		*FRONT TYRE O/S	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,685.70	2,300.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	729.14	370.12
Total Parts (\$\$)	3,956.56	1,930.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	750.00	280.00
5	TO PUTTY & SPRAY PAINTING	New	750.00	400.00
Gross Labour Cost (\$\$)			1,720.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >