



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24080082/Uvp3e2

Date: 28/10/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 8535G	Veh. Inspected	SMF 9288S
Policy No.	D24102460MFCV	Coverage	0
Claim No.	D24006810MFCV	Excess	\$0.00
Assign From	CAROLINE	Assign Date	05/08/2024

2. Vehicle Details

Make & Model	M.G. HS	C.C	1490
Engine No.	15E4E8AGL3160425	Year of Reg.	20/08/2020
Chassis No.	LSJA24U9XLN016310	Colour	RED
Odometer	78040 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50ZR18	MICHELIN	8
L/H Front Tyre	235/50ZR18	MICHELIN	8
R/H Rear Tyre	235/50ZR18	MICHELIN	8
L/H Rear Tyre	235/50ZR18	MICHELIN	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/07/2024	Inspection Date	05/08/2024
Survey held at	AUTO EUROKARS PTE LTD 5 UBI CLOSE, SINGAPORE 408605		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days