

ASS. REC. BY:

REF:

LPC / CS / LPC24080083 / Knb3

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 58K

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 05 days

Res.: Yes or No

Lum Sum: 1.3-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKB 19137Yr Regn: 12, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy CHRC.C. 1797Colour: M. Red

A/C: Insured / Std / NI / NA

Sp. Reading: 115438

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 8YX10

2086525

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 14/8/24D.O.A. 6/8/2024

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/8

6034.90

Car

(Red, # 1020-60, 147)

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$ \_\_\_\_\_)

S + RS. \$ \_\_\_\_\_

☐

Interview (\$ \_\_\_\_\_)

Fees \_\_\_\_\_

☐

Tech Invs (\$ \_\_\_\_\_)

Others \_\_\_\_\_

☐

Weekend (\$ \_\_\_\_\_)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ \_\_\_\_\_)

# ESTIMATE RC AUTO

Not Authorized  
Pulway B4 paint  
5 days  
@ 6034-90

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722  
Tel : 97619383 Email: rcauto5555@gmail.com  
Reg. No. 53199168K

SKB 1913 T

Date : 15.08.2024

| Quantity | Description/Particular             | Unit Price | Amount     |         |
|----------|------------------------------------|------------|------------|---------|
| 1 PC     | REAR BOOTLID 1112.45               |            | By 1207    | 75      |
| 1 PC     | REAR BUMPER SPOILER 1000           |            | By 463     | 60      |
| 1 PC     | REAR END PANEL 731.35              |            | By 892     | 05      |
| 1 PC     | REAR LAMP 768.10                   |            | CM 955     | 60      |
| 1 PC     | REAR BOOTLID GANISH 925.60         |            | CM 1155    | 60      |
| 1 PC     | REAR BUMPER                        |            | By 468     | 20      |
| 1 PC     | REAR END PANEL GANISH              |            | my p 1 316 | 20      |
| 1 PC     | REAR BOOTLID LAMP                  |            | CM 631     | 90      |
| 1 PC     | REAR BUMPER TOWING COVER           |            | Dcl 26     | 80      |
| 1-2 PCS  | REVERSE SENSOR@220                 |            | short 440  | 00      |
|          | Rec bumper reinforcement By 369.00 |            | TOTAL      | 6557 70 |
|          |                                    |            | LESS 25    | 4918 27 |
|          |                                    |            |            |         |
|          | TO REMOVE REAR WINDSCREEN          |            | 180        | 00 1200 |
|          | TO RESPRAY AFFECTED PARTS          |            | 800        | 00 7200 |
|          | TO REPLACE ABOVE PARTS             |            | 800        | 00 6000 |
|          | TO CHECK WIRING                    |            | 30         | 00 200  |
|          | ANTI RUST                          |            | 50         | 00      |
|          |                                    |            |            |         |
|          |                                    |            | TOTAL      | 6778 75 |

Received the above goods in good order and condition

LKK Auto Consultants hence notified

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature E.&O.E.

Date:

for

RC AUTO 7055.50

Received by

Authorised Signature